

To Be Completed by TAG Leads												TAG Meeting Results			
Blue - Current MN Amendment Purple - Code Change Proposal Red - Revisit												Recommendations A - Accept Model Code AM - Amend Model Code R - Reject			
Item Number	2024 IEBC Chapter	2024 IEBC Code Section	2021 IEBC Code Section	2020 MN Code Section	Code Section Heading/Topic	MN Amendment?	Description of change(s) to code language	Safety/Health Value	Cost Impact	Staff Comment	Staff Recommendation	TAG Recommendation	TAG Group Consensus	Stakeholder Consensus	Comments TAG #Y, #N
								N None, L Low, M Med, H High					Y or N	Y or N	
		N.A.	N.A.	1300.0040 Subp. 2	Compliance (the option to use MR 1311 in lieu of MR 1305)	Y		N	N	Coordinate with 1300 TAG	AM				
0-1	0	N.A.	N.A.	1311.0010	General & Mandatory Chapters	Y	Sections contain references to dated editions and code sections which need to be revised for current MSBC	N	N	Revise amendment updating new code sections.	AM				
		N.A.	N.A.	1311.0010 Subp. 3 Item D	Construction Safeguards	Y	Using IBC Ch 33.	N	N	Coordinate with 1305 TAG.	AM				
0-2	0	N.A.	N.A.	1311.0020	References to Other Codes	Y	Modifies & establishes references to other codes.	N	N	Carry over amendment.	AM				
2-1	2	202	202	1305.0202	Ambulatory Care Facility	Y	Definition brought into 2024 IEBC from IBC. MN amended the IBC definition of ACF in MR 1305.	N	N	Ensure definition matches 1305 for the 2026 cycle.	AM				
2-2	2	202	202	1311.0202	Approved	Y	MN amendment more specific than model code	N	N	Carry over amendment	AM				
2-3	2	202			Approved Agency	N	New definition in 2024	N	N		A				
2-4	2	202	202		Change of Occupancy	N	New definition in 2021; Revised definition 2024	N	N	Support - Coordinate with 1305	A				
2-5	2	202	202		Change of Use	N	New definition 2021	N	N	Support - Coordinate with 1305	A				
2-6	2	202		1311.0202	Code	Y	Definition not present in model code	N	N	Carry over amendment	AM				
2-7	2	202	202	1311.0202	Code Official	Y	MN amendment differs from model code	N	N	Carry over amendment	AM				
2-8	2	202	202		Dangerous	N	Revised 2021 - Expands loading conditions; Added 'aftershock' 2024.	L and See Struct.	N and See Struct.	Support - Coordinate with structural.	A				

2-9	2	202	202		Disproportionate Earthquake Damage	N	Revised definition 2024	N	N	Seismic and earthquake provisions made non-applicable elsewhere in MN code.	A				
2-10	2	202	202		Emergency Escape and Rescue Opening	N	New in 2021 IEBC. Same as IBC.	N	N	Support - coordinate with 1305.	A				
2-11	2	202	202	1311.0202	Existing Building	Y	MN amendment more specific than model code.	N	N	Carry over amendment	AM				
2-12	2	202	202		Exterior Wall Covering; Exterior Wall Envelope	N	New in 2021 IEBC. Same as IBC.	N	N		A				
2-13	2	202	202	1311.0202	Historic Building	Y	MN amendment references definition in 1300.0700 Subp. 12a	N	N	Carry over amendment	AM				
2-14	2	202			Listed	N	New in 2024 IEBC. Same as IBC.	N	N		A				
2-15	2	202			Lowest Floor	N	New in 2024 IEBC. Same as IBC.	N	N	Coordinate with 1305.	A				
2-16	2	202			Occupiable Roof	N	New in 2024 IEBC, same as new definition in 2024 IBC.	N	N	Ensure definiton matches 1305 for 2026 cycle.	A				

1311/2024 IEBC Changes Technical Advisory Group (TAG) Review Worksheet

2-17	2	202			Peer Review	N	New in 2024 IEBC, same as new definition in 2024 IBC. Pertains to Storm Shelter design and construction.	N	N	Ensure definition matches 1305 for the 2026 cycle.	A				
2-18	2	202			Photovoltaic Panel System	N	New in 2024 IEBC. Same as IBC.	M	N	Coordinate with 1305.	A				
2-19	2	202		1311.0202	Repair	Y	MN amendment differs from model code.	N	N		AM				
2-20	2	202			Storm Shelter	N	New in 2024 IEBC. Same as IBC.	N	N		A				
2-21	2	202		1311.0202	Substantial Damage	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM				
2-22	2	202			Substantial Improvement	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM				
2-23	2	202			Substantial Structural Damage	N	Small change to language in 2024 - Only the last sentence added to clarify work done to implement repairs shall not be considered damage that reduces structural capacity.	N	N	Coordinate with 1305 & Structural TAG.	A				
2-24	2	202	202		Technically Infeasible	Y	Definition not present in published 1311 MCCEB. See definitions for Technically Infeasible, Accessibility and Technically Infeasible, Stair Construction	No change.	No change.	Addressed in amendments Technically Infeasible Accessibility and Technically Infeasible Stairway Construction.	AM				
2-25	2			1311.0202	Technically Infeasible, Accessibility	Y	Definition not present in model code. Pertains to accessibility in existing buildings.	No change.	No change.	Carry over amendment and duplicate in Rule 1341.	AM				
2-26	2			1311.0202	Technically Infeasible, Stairway Construction	Y	Definition not present in model code.	No change.	No change.	Carry over amendment.	AM				

1311/2024 IEBC Changes Technical Advisory Group (TAG) Review Worksheet

3-1	3	301.1	301.1	301.1	Applicability/General	N	In 2021, new Applicability section (moved from 302) replaces General in 2018	N	N	Coordinate added sections from CCPs. Looks like a good change coordinating sections 302-309 (and then some) applicable to all methods (formerly section 302.1).	AM (CCP's)				
3-2	3	301.1.1	301.1.1		Bleachers	N	Added in 2021 - Refers bleachers to ICC 300.	N	N	Bleacher code ICC 300 will need to be added to 1311.0020 or state adoption and amendments referenced here.	A				
3-3	3	301.3	301.3	301.3	Alteration, Addition, or Change of Occupancy	N	Revised in 2021 - Reorganized and some wordsmithing.	N	N	Discuss Ex. 1 and 2, coordinate 3 with structural.	A				
3-4	3	301.3.1	301.3.1	1311.0301.3.1	Prescriptive Compliance Method	Y	Model codes 2021 and 2024 reference IFC. MN Amendment requires compliance with Ch 5 Prescriptive Compliance.	No change.	No change.	Carry over amendment.	AM				
3-5	3			1311.0301.5	Accessibility in Existing Buildings	Y	Section added. Compliance for accessibility sent to 1341	No change.	No change.	Carry over amendment.	AM				
3-6	3	302.2.1	302.2.1		Health Care Facilities Applicability	N	New subsection. Added in 2021, adds compliance with NFPA 99 Health Care Facilities Code for health care occupancies	H	M	Discuss. Coordinate with 1305 TAG.	A				
3-7	3			1311.0302.3.1	Window Cleaning Anchors	Y	Amendment adds provision for Window cleaning anchors comply with 1305. This will need to be renumbered when carried over (to 302.2.2)	No change.	No change.	Carry over amendment to Rule 1311.0302.2.2 in the 2026 MCCEB.	AM				
3-8	3	302.3	302.3		Existing materials	N	In 2021 changed 'building official' to 'code' official. Also renumbered - was 302.5.	N	N	Discuss. Our current amendment of CODE OFFICIAL in 202 already refers to 1300.0070, subpart 5.	A				
3-9	3	303	303.1; 303.1.1		Storm Shelters (Moved) General; Construction	Y	2021 relocates Storm Shelters from Chapter 11 (Additions) to Chapter 3 (All Compliance Methods). Revised language.	No change.	No change.	Discuss and doordinate with 1305 Ch 4. Amendment needed to specify counties where applicable. Add Mower County to list.	AM				

3-10	3	304			Structural/Seismic	N	Revisions to seismic requirements only.	N	N	Coordinate with Structural TAG. See 1311.0010.	A				
3-10.1	3	305			In-Situ Load Tests		Renumbered in 2021 from 304 to 305.				A				
3-11	3	306		1311.0305 (multiple sections)	Accessibility in Existing Buildings	Y	Changes made in both code cycles. Needs to be renumbered to 1311.0306.	No change.	No change.	Send to 1341 TAG.	AM				
3-12	3	307.1	307.1		Smoke Alarms	y	Moved in 2021 from individual compliance methods to Ch 3 and is applicable to all compliance methods except for the exception. Consider deleting the exception to align with 1309.	M	N	See proposed amendment CCP-EB-1. Also, apply the current amendment to 503.14 here. Consider amendment to delete the exception. (coordinate with 1305 and 1309 TAG's)	AM				
3-12.1	3			1311.0503.14		y	Smoke alarm code sections from other chapters moved to 307. Carry amendment to new smoke alarm location. Renumber to 1311.0307. Amendment points to 1305.	No change.	No change.	(coordinate with 1305 and 1309 TAG's)	AM				
3-13	3	307	307	1311.0307.1, 1311.307.1.1, 1311.307.1.2	Smoke Alarms	Y	Conforms req. for annunciators in dwelling units with Fire Code.	H	L	See CCP-EB-1. Discuss at 6/11 Meeting.					
3-14	3	308	308.1	1311.0503.15	Carbon Monoxide Detection (Moved)	y	Section relocated here in 2021, revision for I-2s in 2024 in exception #4. Added 'E's' in 2021. Removed specific occupancies in the 2024 and changed wording to existing buildings.	H	N	The amendment to 503.15 should to be applied here. Propose amending reference to IBC instead of IFC/IRC and deleting exception #3 (coordinate with 1305 and 1309 TAG's)	AM				
3-14.1	3			1311.0503.15	Carbon Monoxide Alarms	Y	Carry amendment from Ch 5 to new location.	H	N	(coordinate with 1305 and 1309 TAG's)	AM				
3-15	3	309	309		Add & Replace Ext Wall Covering & Envelope	N	Section added in 2021, revision for high rises in 2024.	L	L		A				
3-16	3			1311.0310	Energy Code for Existing Buildings	Y		H	M	See CCP-EB-2. All references in IEBC to 1322 and 1323 per 1311.0020.					

3-17	3			1311.0310	Energy Conservation	Y		H	M	See CCP-EB-3. All references in IEBC to 1322 and 1323 per 1311.0020.				
3-18	3			1311.0311	Electric Vehicle Charging Stations	Y	Adds scoping for EV charging stations	H	M	See CCP-EB-4. Support, but need cost benefit analysis information.				
4-1	4		401.1.1		Bleachers, etc.	N	New in 2021 - Repairs shall comply with ICC 300.	M	N	Bleacher code ICC 300 will need to be added to 1311.0020 or state adoption and amendments referenced here.	AM			
4-2	4	401.2			Compliance	N	2024 adds language for nondamaged components incidental to repair.	M	N	We see no issue.	A			
4-3	4	405	405	405	Structural	Y	Minor change 2021. More changes 2024.	See Struct.	See Struct.	Send to Structural TAG.	A			
4-4	4			1311.0405.2.4	Substantial Structural Damage to Gravity Load-Carrying Components	Y	Amendment requires demonstration that components have capacity to carry design loads of rehab design. Current amendment and also new language in model code.	See Struct.	See Struct.	Send to Structural TAG.	AM			
4-5	4	406.1	406.1		General Electrical	N	Changes "material" to "general". Requires repairs to comply with NFPA 70. Previously, allowed to be replaced with like material.	L	L	DLI/CCLD Electrical Unit is aware.	A			
4-6	4	406.1.1	406.1.1		Reconditioned Electrical Equipment	N	Eliminates "Receptacles" section, replaces with requirement for reconditioned equipment to comply with NFPA 70 or NFPA 99.	L	L	DLI/CCLD Electrical Unit is aware.	A			
4-7	4	406.1.2	406.1.2		Plug Fuses - Deleted	N	Eliminated in 2024.	L	L	DLI/CCLD Electrical Unit is aware.	A			
4-8	4	406.1.2	406.1.4		Health Care Facilities (Electrical)	N	Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics repairs shall comply with NFPA 99.	H	M	DLI/CCLD Electrical Unit is aware.	A			
4-9	4	408.3	408.3		Health Care Facilities (Plumbing)	N	Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics med gas system repairs shall comply with NFPA 99.	H	M	Consistent with Electrical code sections.	A			