

To Be Completed by TAG Leads											TAG Meeting Results				
1309/IRC Structural Review											Recommendations A - Accept Model Code AM - Amend Model Code R - Reject				
Item No.	2024 Code and Chapter		2024 Section	2021 Code Section	2020 MN Code / MR Code Section	Code Section Heading/Topic	MN Amendment?	Description of change(s) to code language	Safety/Health Value	Cost Impact	Staff Recommendation	TAG Recommendation	TAG Group Consensus	Stakeholder Consensus	Comments
	Code	Chapter											Y or N	Y or N	
Chapter 3 Building Planning															
Chapter 4 Foundations															
48R	IRC	4	R404.1.1	R404.1.1	1309.0404.1.1	Foundations, Foundations and Retaining Walls, Concrete and Masonry Foundation Walls, Design Required	Y	Current MR: Adds exception to design required: "Cantilevered concrete and masonry foundation walls supporting unbalanced backfill that do not have permanent lateral support at the top of the foundation shall be constructed according to Table R404.1.1(5), Table R404.1.1(6), or Table R404.1.1(7)."				Tabled			Tabled 2/6/25. Related CCP (50R) to be reviewed at a future TAG. Bring in line with accepted engineering practices and eliminate inconsistencies where possible. 3/27/25 tabled.
50R	IRC	4	~	~	Tables 1309.0404.1.1(5); 1309.0404.1.1(6); 1309.0404.1.1(7)	Cantilevered Concrete and Masonry Foundation Walls	Y	Current MR: Tables added				Tabled			Tabled 2/6/25. CCP to be reviewed at a future TAG. Bring in line with accepted engineering practices and eliminate inconsistencies where possible. 3/27/25 tabled.
53.1R	IRC	4			CCP-STR-10-Res R403.1.6.1	Sill Plate Overhang		Code change proposal.			Craig Oswell				
Chapter 6 Wall Construction															
Chapter 7 Wall Covering - No Structural Changes															
Chapter 8 Roof-Ceiling Construction															
Chapter 9 Roof Assemblies															
Chapter 10 Chimneys & Fireplaces - No Structural Changes															