

[Link to 2024 IEBC \(changes in blue\)](#)

[Link to 2021 IEBC \(changes in blue\)](#)

To Be Completed by TAG Leads												TAG Meeting Results			
Blue - Current MN Amendment Purple - Code Change Proposal Red - Revisit												Recommendations A - Accept Model Code AM - Amend Model Code R - Reject			
Item Number	2024 IEBC Chapter	2024 IEBC Code Section	2021 IEBC Code Section	2020 MN Code Section	Code Section Heading/Topic	MN Amendment?	Description of change(s) to code language	Safety/Health Value	Cost Impact	Staff Comment	Staff Recommendation	TAG Recommendation	TAG Group Consensus	Stakeholder Consensus	Comments
								N - None, L - Low, M-Med, H-High					Y or N	Y or N	
1311.0010 Adoption and 1311.0020 References to other Codes															
0-1				1300.0040 Subp. 2	Compliance	Y		N	N	Coordinate with 1300 TAG	AM	NA	Y		No recommendation needed. 1300 TAG will address.
0-1	0			1311.0010	General & Mandatory Chapters	Y	Sections contain references to dated editions and code sections which need to be revised for current MSBC	N	N	Revise amendment.	AM*	AM	Y		Revise amend. to correct dates.
0-1.2				1311.0010 Subp. 3 Item D	Construction Safeguards	Y	Using IBC Ch 33.			Coordinate with 1305 TAG.	AM*	AM	Y		Coordinate with 1305 TAG and a CCP related to this section.
0-2	0			1311.0020	References to Other Codes	Y	Modifies & establishes references to other codes.	N	N	Carry over amendment.	AM	AM	Y		Carry over amendment.
Chapter 2 Definitions															
2-1	2	202		1305.0202	Ambulatory Care Facility	Y	Definition brought into 2024 IEBC from IBC. MN amended the IBC definition of ACF in MR 1305.	N	N	Ensure definition matches 1305 for the 2026 cycle.	AM*	A	Y		Coordinate with 1300 and 1305 TAGs. Revisit.
2-2	2	202	202	1311.0202	Approved	Y	MN amendment more specific than model code	N	N	Carry over amendment	AM	AM	Y		
2-3	2	202			Approved Agency	N	New definition in 2024	N	N		A	A	Y		
2-4	2	202	202		Change of Occupancy	N	New definition in 2021; Revised definition 2024	N	N	Support - Coordinate with 1305	A*	A	Y		Coordinate with 1305 TAG. New definition qualifies a "change of occupancy" to when code requires a <u>greater degree of safety</u> .
2-5	2	202	202		Change of Use	N	New definition 2021	N	N	Support - Coordinate with 1305	A	A	Y		Discussion. Support.
2-6	2	202		1311.0202	Code	Y	Definition not present in model code	N	N	Carry over amendment	AM	A	Y		Carry over amendment
2-7	2	202	202		Code Official	Y	MN amendment differs from model code	N	N	Carry over amendment	AM	A	Y		Carry over amendment
2-8	2	202	202		Dangerous	N	Revised 2021 - Expands loading conditions; Added 'aftershock' 2024.	L	N	Support - Coordinate with structural.	A	A	Y		(Structural TAG recommends accepting.)

2-9	2	202			Disproportionate Earthquake Damage	N	Revised definition 2024	N	N	Seismic and earthquake provisions made non-applicable elsewhere in MN code.	A	A	Y		Seismic and earthquake provisions made non-applicable elsewhere in MN code.
2-10	2	202	202		Emergency Escape and Rescue Opening	N	New in 2021 IEBC. Same as IBC.	N	N	Support - coordinate with 1305.	A*	A	Y		Staff coordination with 1305 and 1309.
2-11	2	202	202	1311.0202	Existing Building	Y	MN amendment more specific than model code.	N	N	Carry over amendment	AM	AM	Y		Carry over amendment.
2-12	2	202	202		Exterior Wall Covering; Exterior Wall Envelope	N	New in 2021 IEBC. Same as IBC.	N	N		A	A	Y		
2-13	2	202	202	1311.0202	Historic Building	Y	MN amendment references definition in 1300.0700 Subp. 12a	N	N	Carry over amendment	AM	AM	Y		Carry over amendment.
2-14	2	202			Listed	N	New in 2024 IEBC. Same as IBC.	N	N		A	A	Y		
2-15	2	202			Lowest Floor	N	New in 2024 IEBC. Same as IBC.	N	N	Coordinate with 1305.	A	A	Y		(1305 TAG recommends accept 2024 IBC definition.)
2-16	2	202			Occupiable Roof	N	New in 2024 IEBC, same as new definition in 2024 IBC.	N	N	Ensure definition matches 1305 for 2026 cycle.	A	A	Y		(1305 TAG recommends accept 2024 IBC definition.)
2-17	2	202			Peer Review	N	New in 2024 IEBC, same as new definition in 2024 IBC. Pertains to Storm Shelter design and construction.	N	N	Ensure definition matches 1305 for the 2026 cycle.	A	A	Y		Some discussion. (1305 TAG recommends accept 2024 IBC definition.)
2-18	2	202			Photovoltaic Panel System	N	New in 2024 IEBC. Same as IBC.			Coordinate with 1305.	A	A	Y		
2-19	2	202		1311.0202	Repair	Y	MN amendment differs from model code.	N	N		AM	AM	Y		
2-20	2	202			Storm Shelter	N	New in 2024 IEBC. Same as IBC.	N	N		A	A	Y		
2-21	2	202		1311.0202	Substantial Damage	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM	AM	Y		Discussion. JB to research. Amendment removes 'floodplain' because flood regs are in MR 1335, not 1311. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.
2-22	2	202		1311.0202	Substantial Improvement	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM	AM	Y		Discussion. JB to research. Amendment removes 'floodplain' because flood regs are in MR 1335, not 1311. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.
2-23	2	202			Substantial Structural Damage	N	Small change to language in 2024 - Only the last sentence added to clarify work done to implement repairs shall not be considered damage that reduces structural capacity.	N	N	Coordinate with 1305 & Structural TAG. Structural TAG recommends accept change.	A	A	Y		Discussion. Tabled. JB to research. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.

2-24	2	202	202		Technically Infeasible	Y	Definition not present in published 1311 MCCEB. See definitions for Technically Infeasible, Accessibility and Technically Infeasible, Stair Construction	N	N	Addressed in amendments Technically Infeasible Accessibility and Technically Infeasible Stairway Construction.	AM	AM	Y		Relates to Accessibility, which is purview of 1341 TAG. Replaced with amendment only adding "Accessibility" to defined term to distinguish from "Technically Infeasible, Stairways". No change in application.
2-25	2			1311.0202	Technically Infeasible, Accessibility	Y	Definition not present in model code. Pertains to accessibility in existing buildings.	N	N	Check with 1341 TAG chair and rules coordinator.	AM	AM	Y		Relates to Accessibility, which is purview of 1341 TAG. Amendment only adds "Accessibility" to defined term to distinguish from "Technically Infeasible, Stairways". No change in application.
2-26	2			1311.0202	Technically Infeasible, Stair Construction	Y	Definition not present in model code.	N	N	Carry over amendment.	AM*				Discussion. Some interest in why only limited to stairway. Amendment <i>expands</i> availability of technically infeasible beyond the model code language. Revisit. 4/30-MB to research amendment.
Chapter 3 Provisions for All Compliance Methods															
3-1	3	301.1	301.1	301.1	Applicability/General	N	In 2021, new Applicability section (moved from 302) replaces General in 2018	N	N	Coordinate added sections from CCPs. Looks like a good change coordinating sections 302-309 (and then some) applicable to all methods (formerly section 302.1).	AM (if CCP's)*	A or AM if needed	Y		Will only need amendment if CCP's extend numbered sections.
3-2	3	301.1.1	301.1.1		Bleachers		Added in 2021 - Refers bleachers to ICC 300.	H	L	Bleacher code ICC 300 will need to be added to 1311.0020 or state adoption and amendments referenced here.	A	A	Y		
3-3	3	301.3	301.3	301.3	Alteration, Addition, or Change of Occupancy		Revised in 2021 - Reorganized and removes accessibility.	N	N	Discuss Ex. 1 and 2, coordinate 3 with structural.	A*	A	Y		Discussion. No substantive change in application except that Ex. 1 exempts accessibility, which is the purview of 1341 TAG. Coordinate with Structural.

3-4	3	301.3.1	301.3.1	1311.0301.3.1	Prescriptive Compliance Methods	Y	Model codes 2021 and 2024 reference IFC. MN Amendment requires compliance with Ch 5 Prescriptive Compliance.	N	N	Carry over amendment.	AM				Consensus not unanimous. Fire Code still applies, administered by Dept. of Public Safety, not CCLD. Table 4/30.
3-5	3			1311.0301.5	Accessibility in Existing Buildings	Y	Section added. Compliance for accessibility sent to 1341	N	N	Carry over amendment.	AM*	A	Y		Carry over amendment - sent accessibility to 1341.
3-5.1	3	302.2			Additional Codes		List of other codes applicable to existing buildings.	N	N	Review for consistency with MN adopted codes.	A	A	Y		
3-6	3	302.2.1	302.2.1		Health Care Facilities Applicability		New subsection. Added in 2021, adds compliance with NFPA 99 Health Care Facilities Code for health care occupancies	N	N	Discuss.	A	A	Y		Discussion. Added in 2021, no change in 2024. Currently NFPA 99 referenced in 1311 and 1305.
3-7	3			1311.0302.3.1	Window Cleaning Anchors	Y	Amendment adds provision for Window cleaning anchors comply with 1305. This will need to be renumbered if carried over (to 302.2.2)	N	N	Carry over amendment.	AM	AM	Y		Carry over amendment.
3-8	3	302.3	302.3		Existing materials		In 2021 changed 'building official' to 'code' official. Also renumbered - was 302.5.	N	N	Discuss. Our current amendment of CODE OFFICIAL in 202 already refers to 1300.0070, subpart 5.	A	A	Y		Discussion. Our current amendment of CODE OFFICIAL in 202 already refers to 1300.0070, subpart 5.
3-9	3	303	303.1; 303.1.1		Storm Shelters (Moved) General; Construction		2021 relocates Storm Shelters from Chapter 11 (Additions) to Chapter 3 (All Compliance Methods). Revised language.	N	N	Discuss and coordinate with 1305 Ch 4. Amendment needed to specify counties where applicable. Add Mower County to list.	AM*	AM	Y		Discuss and coordinate with 1305 Ch 4. Amendment needed to specify counties where applicable. Add Mower County to list.
3-10	3	304			Structural/Seismic		Revisions to seismic requirements only.	N	N	Coordinate with Structural TAG.	A	A	Y		(Structural TAG recommending acceptance of seismic references throughout model IBC and ICEB because MR 1305.0011 Subp. 4 and 1311.0010 Subp. 4 deletes any references to earthquake or seismic provisions.)
3-10.1	3	305			In-Situ Load Tests		Renumbered in 2021 from 304 to 305.				A	A	Y		
3-11	3	306		1311.0305 (multiple sections)	Accessibility in Existing Buildings	Y	Changes made in both code cycles. Needs to be renumbered to 1311.0306.	N	N	Send to 1341 TAG.	AM*	A	Y		All accessibility to 1341 TAG.

3-12	3	307.1	307.1		Smoke Alarms	y	Moved in 2021 from individual compliance methods to Ch 3 and is applicable to all compliance methods except for the exception. Consider deleting the exception to align with 1309.	H	N	See proposed amendment CCP-EB-1. Also, apply the current amendment to 503.14 here. Consider amendment to delete the exception. (coordinate with 1305 and 1309 TAG's)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-12.1	3			1311.0503.14		y	Smoke alarm code sections from other chapters moved to 307. Carry amendment to new smoke alarm location. Renumber to 1311.0307. Amendment points to 1305.	No change.	No change.	(coordinate with 1305 and 1309 TAG's)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-13	3	307	307	1311.0307.1, 1311.307.1.1, 1311.307.1.2	Smoke Alarms	Y	Conforms req. for annunciators in dwelling units with Fire Code.	H	L	See CCP-EB-1. Discuss at 6/11 Meeting.	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-14	3	308	308.1	1311.0503.15	Carbon Monoxide Detection (Moved)	y	Section relocated here in 2021, revision for I-2s in 2024 in exception #4. Added 'E's' in 2021. Removed specific occupancies in the 2024 and changed wording to existing buildings.	H	N	The amendment to 503.15 should be applied here. Propose amending reference to IBC instead of IFC/IRC and deleting exception #3 (coordinate with 1305 and 1309 TAG's)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-14.1	3			1311.0503.15	Carbon Monoxide Alarms	Y	Carry amendment from Ch 5 to new location.	H	N	(coordinate with 1305 and 1309 TAGs).	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-15	3	309	309		Add & Replace Ext Wall Covering & Envelope	N	Section added in 2021, revision for high rises in 2024.	H	M		A	A	Y	Public member concerned with scope of requirements. MB to research reason for addition in model code.	
3-16	3			1311.0310	Energy Code for Existing Buildings	Y		L	M	See CCP-EB-2. All references in IEBC to 1322 and 1323 per 1311.0020.				Table until June 11 meeting when proponent for related CCPs present at meeting.	
3-17	3			1311.0310	Energy Conservation	Y		L	M	See CCP-EB-3. All references in IEBC to 1322 and 1323 per 1311.0020.				Table until June 11 meeting when proponent for related CCPs present at meeting.	

3-18	3			1311.0311	Electric Vehicle Charging Stations	Y	Adds scoping for EV charging stations	L	M	See CCP-EB-4. Support, but need cost benefit analysis information.					Table until June 11 meeting when proponent for related CCPs present at meeting.
Chapter 4 Repairs															
4-1	4		401.1.1		Bleachers, etc.		New in 2021 - Repairs shall comply with ICC 300.	H	L		A	A	Y		
4-2	4	401.2			Compliance		2024 adds language for nondamaged components incidental to repair.	N	L		A	A	Y		
4-3	4	405	405	405	Structural	Y	Minor change 2021. More changes 2024.	H	M	Send to Structural TAG.	A*	A	Y		Coordinate with Structural TAG.
4-4	4			1311.0405.2.4	Substantial Structural Damage to Gravity Load-Carrying Components	Y	Amendment requires demonstration that components have capacity to carry design loads of rehab design. Current amendment and also new language in model code.	H	M	Send to Structural TAG.	AM*	AM	Y		Discussion. Public member concerned with scope of requirements. Has been in code since 2006. Priority for recommendation to Structural TAG.
4-5	4	406.1	406.1		General Electrical		Changes "material" to "general". Requires repairs to comply with NFPA 70. Previously, allowed to be replaced with like material.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-6	4	406.1.1	406.1.1		Reconditioned Electrical Equipment		Eliminates "Receptacles" section, replaces with requirement for reconditioned equipment to comply with NFPA 70 or NFPA 99.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-7	4	406.1.2	406.1.2		Plug Fuses - Deleted		Eliminated in 2024.	N	N	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-8	4	406.1.2	406.1.4		Health Care Facilities (Electrical)		Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics repairs shall comply with NFPA 99.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-9	4	408.3	408.3		Health Care Facilities (Plumbing)		Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics med gas system repairs shall comply with NFPA 99.	H	M		A	A	Y		
Chapter 5 Prescriptive Compliance Method															
5-1	5	501.3	501.3		Health Care Facilities (Prescriptive Compliance)		Added in 2021, Group I-2, ambulatory care facilities and outpatient clinics alterations and additions electrical or med gas systems shall comply with NFPA 99.	H	L		A	A	Y		
5-2	5	502.1	502.1		General (Additions)		Revised in 2024 - limits some structural compliance requirements, specifies addition of occupiable roof shall comply with IBC (with exception).	M		Coordinate with Structural TAG and obtain input on cost.	*	A	Y		Coordinate with Structural.

5-3	5	502.1.1			Risk Category Assignment (Additions)		New in 2024.	M		Coordinate with Structural; TAG and obtain input on cost.	*	A	Y		Coordinate with Structural.
5-4	5	502.1.2			Creation or Extension of Nonconformity (Additions)		New in 2024 (with exception).	H		Coordinate with Structural TAG and obtain input on cost.	*	A	Y		Coordinate with Structural.
5-5	5		502.2		Disproportionate Earthquake Damage (Additions) - Deleted		Eliminated in 2024.				A	A	Y		
5-6	5	502.2		502.3	Flood Hazard Areas (Additions)		Renumbered and revised in 2024.			Coordinate with MR 1335 Floodproofing Regs.	A	A	Y		
5-7	5	502.3	502.4	MR 1311.502.4	Existing Structural Elements Carrying Gravity Loads (Additions)	y	Renumbered in 2024.			Send to Structural TAG.	*	A	Y		
5-8	5	502.4	502.5	MR 1311.0502.5	Existing Structural Elements Carrying Lateral Loads (Additions)	Y	Renumbered and revised in 2024.			Send to Structural TAG.	*	A	Y		
5-9	5	502.5			Smoke Barriers in Group I-1, Cond. 2 (Additions)		New in 2024. Addresses smoke barriers in additions to I-1 Cond. 2.	H	L		A	A	Y		
5-10	5		502.6	1311.0502.6	Smoke Alarms in Existing Portions of a Building (Additions) - Relocated	Y	Relocated in 2021. Now addressed in 307.1. See also CCP-EB-1.	H	L	Amendment not needed here - address in 307.1.	AM*	AM	Y		Amendment to be in Ch. 3.
5-11	5	502.6	502.6		Enhanced Classroom Acoustics (Additions)		New in 2021. Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberance only.	H	M	Coordinate with 1341 TAG.	A*				Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberance only.
5-12	5	503.1	503.1	1311.0503.1	General (Alterations)	Y	Reworded in 2021, structural revision in 2024. MN amendment modifies exceptions.			Coordinate with Structural TAG. Review language.	AM*	A	Y		
5-13	5	503.3		1311.0503.3	Existing Structural Elements Carrying Gravity Load (Alterations)	Y	No changes in 2021 or 2024.			Send to Structural TAG.	AM*				Send to Structural TAG.
5-14	5	503.4	503.4	1311.0503.4	Existing Structural Elements Carrying Lateral Loads (Alterations)	Y	Exceptions 1 revised & 2 added in 2021. Further revision of Exception 1, and addition of Exception 3 in 2024 related to seismic. MN amendment rewords Exception 1.			Send to Structural TAG.	AM*				Send to Structural TAG.
5-15	5	503.5			Seismic Design Category F		Seismic revised in 2024. Proposed CC-P to replace with Reroofing.			See proposed amendment CCP-EB-5 replacing this section.					Table until June 11 meeting when proponent for related CCPs present at meeting.
5-16	5	503.5		1311.0503.5	Reroofing (Alterations)		Proposal deletes seismic provision, replaces with direction to comply with 1305 for reroofing.			See CCP-EB-5. Also CCP-EB-7					Table until June 11 meeting when proponent for related CCPs present at meeting.

5-17	5	503.6, 503.7, 503.8, 503.9, 503.10, 503.11, 503.12, 503.13			Bracing and Anchorage for Parapets, Bracing and Anchorage for Masonry Walls, Substantial Structural Alteration, Roof Diaphragms Resisting Wind Loads, Voluntary Lateral-Force Resisting Systems (Alterations)		Several 2024 changes in these sections, some referencing IEBC Ch 3. Roof Diaphragm revised 2021 and 2024.			Send to Structural TAG.	*				Send to Structural TAG.
5-18	5	503.14	503.14		Smoke Compartments (Alterations)		Relocated 2021. Was under Refuge Areas. Addresses smoke compartments in I-2s for alterations. Language changed in 2021. No changes in 2024.	L	L		A	A	Y		
5-19	5			1311.0503.14	Smoke Alarms in Existing Portions of a Building (Alterations) - Relocated to 307.1	Y	Smoke alarms relocated to 307.1 in 2021. See also CCP-EB-1. One exception added.	H	L	Current amendment to 503.14 not needed here 307.1 needs this amendment.	AM				Table until June 11 meeting when proponent for related CCPs present at meeting.
5-19	5			1311.0503.15	Carbon Monoxide Alarms	Y	CO alarms relocated to 308 in 2021. Two exceptions added.	H	L	Current amendment to 503.15 not needed here. 308 needs amendment.	AM				Table until June 11 meeting when proponent for related CCPs present at meeting.
5-20	5	503.15	503.15		Refuge Areas		Revised in 2021. Minor change in 2024.	H	L	From 2018: 503.16.1 Smoke Compartments now in 503.14; 503.16.2 Ambulatory Care now in 503.17; 503.16.3 Horizontal Exits address here in 503.15.	A	A	y		
5-21	5	503.16, 503.16.1			Conditions for Group I-1 Occupancies; Smoke Barriers in Group I-1, Cond. 2		New in 2024.	H	M		A	A	Y		
5-22	5	503.17			Ambulatory Care Facilities		New language in 2024. Was under Refuge Areas.	H	M		A	A	Y		
5-23	5	503.18	503.16		Enhanced Classroom Acoustics (Alterations)		New in 2021. Renumbered in 2024	H	M	Coordinate with 1341.	A				Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberance only.
5-24	5	503.19	503.17		Locking Arrangements in Educational Occupancies		New in 2021. Renumbered in 2024. Reference to IBC numbering is incorrect in model code. Should be 1010.2.7.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A	A	Y		

5-25	5	503.20	503.18		Two-Way Communication Systems		New in 2021. Renumbered in 2024.	H	M		A	A	Y		
5-25.1	5			1311.503.21	Elevator Hoistway Opening Protection	Y				See CCP-EB-6					
5-25.2	5	504.4		1311.504.4	Fire Escapes, Dimensions			M	L	Carry over.	AM	AM	Y		
5-26	5	505.1	505.1	505.1	Replacement Windows		Changed "glass" to "windows" in 2021. No change in 2024.	L	L		A*				Discussion, Window manf.'s instructions don't cover existing buildings. Mike to research. Revisit.
5-27	5	505.2	505.2	505.2	Window Fall Prevention on Replacement Windows		Sub-section revised in 2021. Renamed in 2024 from "Window Opening Control Devices on Replacement Windows" to new heading.	H	L		A	A	Y		
5-28	5	505.3; 505.3.1	505.3; 503.3.1	505.3	Replacement Window Emergency Escape and Rescue Openings		Some changes in 2021, including separating Control Devices to a sub-section. Only revised IRC citation in 2024.	H	L		A	A	Y		
5-29	5			1311.0505.3.1	Licensed Facilities	Y	Addresses requirements for foster care, day care licensed or registered by the State.	H	L	Coordinate with Fire Code	AM	AM	Y		
5-30	5	505.4	505.4		Bars, Grilles, Covers or Screens		Renamed in 2021 to "Bars, Grilles, Covers or Screens". Was "Emergency Escape and Rescue Openings"	H	L		A	A	Y		
5-30.1	5			1311.0505.4	Windows and Emergency Escape Openings	Y	Amendment removes reference to Smoke Alarms in model code. Smoke Alarms are addressed elsewhere.	H	L	Revise amendment to address 505.4 Item 4.	R	R	Y		Delete amendment. Accept model code.
5-31	5	506.1	506.1	1311.0506.1	Compliance	Y	MN amendment references the Life-Safety and Fire Risk Table 506.1.	H	L	Carry over.	AM	AM	Y		
5-31.1	5			CCP-EB-8	Table - Prescriptive Life Safety & Fire Risk		Proposed revision to MR Table 506.1	H	L	Review 2018 SONAR for the original amendment.					
5-32	5			1311.0506.1.2	Small Assembly Spaces	Y	Language similar to IBC Ch 3.	M	L	Carry over.	AM				MB to research
5-33	5	506.4	506.4		Existing Emergency Escape and Rescue Openings (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Coordinate with 1305 and 7511.	AM*				
5-34	5	506.5.3	506.5.3; 506.5.4	506.4.3; 506.4.4	Seismic Loads (seismic force-resisting system); Access to Risk Category IV		Changes in 2021 and 2024			Priority Structural	A*				Coordinate with Structural for Risk Categories.
5-35	5	506.6	506.6		Enhanced Classroom Acoustics (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Coordinate with 1341.	A				Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberance only.
Chapter 6 Classification of Work (Work Area Compliance)															

6-1	6	601.1			General Scope		Change in 2024. Removes moved buildings from scope for Classification of Work method.	L	L		A				
6-2	6	603.1	603.1		Scope		Change in 2021. Adds qualifier that Level 2 Alterations are work area less than 50% of building area where within the scope of work described. Exception clarifies exempt items.	L	L		A				
Chapter 7 Alterations - Level 1															
7-1	7	701.3			Flood Hazard Areas Level 1 Alterations		Change in numbering for work in flood hazard area. MR 1311.0010 Subp. 3, C already sends this to MR Chapter 1335	L	L		A				
7-2	7	702.4	702.4		Window Fall Prevention		2021 changes "bottom of sill" to "bottom of the clear opening". 2024 Changes title of section and adds "or other window fall prevention devices".	H	L	Confirm consistent with 1305 and 1309.	A				
7-3	7	702.5	702.5		Replacement Window for Emergency Escape and Rescue Openings		2021 added "for" in section title. Renumbered reference to IRC and IBC sections. Sends replacement windows for change of occupancy to IEBC Ch 10.	H	L		AM				
7-4	7			1311.0702	Replacement Window Emergency Escape and Rescue Openings; Licensed Facilities	Y	Amends and adds subsection 702.5.1. Removes reference to IRC buildings; combines window opening control devices (found in subsection 702.5.1 in model codes) to main section. Added subsection 702.5.1 addresses foster care or day care licensed or registered by state of MN.	H	L	Need amendment to remove IRC buildings. Could leave Control Devices as 702.5.1 and make Licensed Facilities 702.5.2. Must confirm provisions for licensed facilities include all relevant types of licenses and that req.'s match MDH and MN Fire Code. Renumber from 702.5.1 to 702.5.2 and carry forward.	AM*				
7-5	7	702.5.1	702.5.1		Control Devices (Replacement EEROs)		New sub-section for control devices for replacement EEROs added in 2021.	H	L		A				
7-6	7	702.6	702.6		Bars, Grilles, Covers or Screens		New section in 2021. Allows if meeting clear opening for code under which building was constructed.	H	L	Amend to be consistent with 1311.0505.4.	AM				
7-7	7	704.1.1	704.1.1		Projections in Nursing Home Corridors (Means of Egress)		New in 2021.	H	L		A				
7-8	7	704.2	704.2		Casework (MOE)		New in 2021	H	L		A				

7-9	7	704.3	704.3		Locking Arrangements in Educational Occupancies (MOE)		New in 2021. Includes E, B ed occupancies, and I-4.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A				
7-10	7				General - Reroofing		CCP for Ex. 2			See CCP-EB-7					
7-11	7	705.1			General - Reroofing		For Ex. 1 and 2, adds requirement to comply with IBC Snow and Rain Loads			Send to Structural TAG.	*				
7-12	7		705.2		Structural and Construction Loads		Section deleted in 2021.			Send to Structural TAG.	*				
7-13	7	705.2			Roof Replacement		Changed in 2024. Now 3 exceptions to removal of all existing layers of coverings down to deck.	L	L		A				
7-14	7	705.3			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024.	L	L		A				
7-15	7	705.3.1			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024; Renamed in 2024; Added "panel products" to gypsum in 2024.	L	L		A				
7-16	7			1311.0706.2	Addition or Replacement of Roofing or Replacement of Equipment	Y				Send to Structural TAG.	*				
7-17	7	706.3.1			Bracing for Unreinforced Masonry Bearing Wall Parapets		Change in 2024.			Send to Structural TAG.	*				
7-18	7	706.3.2	706.3.2		Roof Diaphragms Resisting Wind Loads in High-Wing Regions		Change in 2021 and again in 2024.			Send to Structural TAG.	*				
7-19	7	707	707		Health Care Facilities		Added in 2021. I-2s, ACFs, outpatient clinics altered electrical systems comply with NFPA 99.	H	L	Electrical unit is aware of change.	A				
7-20	7	708		1311.0707	Energy Conservation	Y	Sends Ch 7 Energy to MN Energy Code 1322 and 1323	M	M		AM				
Chapter 8 Alterations - Level 2															
8-1	8			1311.0801.1	Work Area Method Level 2 General, Scope	Y	MN amendment deletes exception for reconfig for accessibility.	N	N		AM				
8-2	8	801.3	801.3		L2 System Installations		New in 2021. Requirements related to work area are not applicable where the Level 2 alterations are limited solely to mech, elec, fire prot., haz mat abatement, windows, hardware, op. controls, elec. outlets, signs, alterations primarily for accessibility.	N	L		A				
8-3	8	802.4	802.4		L2 Interior Finish		Change in 2021. Adds 'trim', clarifies exception, adds testing.	N	N		A				
8-4	8	802.4.1	802.4.1		L2 Supplemental Interior Finish Requirements		Change in 2021. Adds 'trim'.	N	N		A				

8-5	8	803.2.2	803.2.2		L2 Automatic Sprinkler Systems, Specific Occupancy Groups		Change in 2021. Breaks out I occupancies.	N	N		A				
8-6	8	803.2.2 Ex.			L2 Automatic Sprinkler Systems, Specific Occupancy Groups		Change in 2024. For specific occupancy groups, revises (clarifies?) the exception for no water available-then smoke detection req.	H	N		A				
8-7	8	803.2.3	803.2.3		L2 Automatic Sprinkler Systems, Group I-2		Change in 2021. Sprinkler reqs for I-2s.	H	M		A				
8-8	8	803.2.5	803.2.5		L2 Automatic Sprinkler Systems, Other Required Automatic Sprinkler Systems		New in 2021. Requirements related to work area with shared exits or corridors by more than one tenant or occ load greater than 30, work area requires sprinklers.	H	M		A				
8-9	8	803.2.5			L2 Automatic Sprinkler Systems, Other Required Automatic Sprinkler Systems		Change in 2024. For other buildings and areas listed in IBC T 903.2.11.6, revises (clarifies?) the condition where sprinklers req.	H	N		A				
8-10	8	803.2.6	803.2.6		L2 Automatic Sprinkler System Supervision		Change in 2021. Clarifies Ex. 1.	N	N		A				
8-11	8	803.2.6			L2 Automatic Sprinkler System Supervision		Change in 2024. References IBC 903.4 for sprinkler supervision.	H	L		A				
8-12	8	803.4			L2 Fire Alarm and Detection		Changes in 2024. Reorganizes, specifies reference to IFC CH 11 for several occupancies.	H	N		A				
8-13	8	803.4.1.1			L2 Fire Alarm and Detection, Group E		Change in 2024. Specifies reverence to IFC Ch 11.	H	N		A				
8-14	8	803.4.1.2	803.4.1.2		L2 Fire Alarm and Detection, Group I-1		Change in 2021. Removed "residential care/ assisted living".	H	N		A				
8-15	8	803.4.1.3	803.4.1.3		L2 Fire Alarm and Detection, Group I-2		Change in 2021. Specifies reference to IFC Ch 11.	H	N		A				
8-16	8	803.4.1.5			L2 Fire Alarm and Detection, Group R-1		Change in 2024. Specifies reverence to IFC Ch 11.	H	N		A				
8-17	8	803.4.3			L2 Fire Alarm and Detection, Installation		Change in 2024 reorganization of section. This basic language was in 803.4, requires compliance with IBC 907 and NFPA 72.	H	N		A				
8-18	8	804.3	804.3	805	L2 Means of Egress, Group I-2		New section 2021. In I-2s, where corridors are used for movement of beds, ramps and corridors to be 48" or more. (All of Means of Egress renumbered in 2021 from 805 to 804.)	H	M		A				
8-19	8			1311.0805.2	L2 Means of Egress, General	Y	MN amendment.	N	N		AM				
8-20	8	804.4	804.11	805.10	L2 Refuge Areas		Revised in 2021. Moved in 2024 to 804.4.	H	L		A				
8-21	8	804.5; 804.5.1			L2 Means of Egress, Refuge Areas; Number of Exits		Renumbered in 2024. Adds "or access to exits" and changes "occupied roof to "occupiable roof".	H	N		A				

8-22	8	804.5.1.1	804.4.1.1	805.3.1.1	L2 Means of Egress, Single-Exit Buildings		2021 changes "non-sprinklered" to "without an approved automatic sprinkler system". 2024 changes "occupied roof" to "occupiable roof".	H	M	Further research on origin and impact of changes needed.	*				
8-23	8	Table 804.5.1.1(1)	Table 804.4.1.1(1)	Table 805.3.1.1(1)	L2 Means of Egress, Stories with One Exit or Access to One Exit for R-2 Occupancies		2021 changes footnote a - "non-sprinklered" to "without an approved automatic sprinkler system". In 2024, increases to 3rd story, 125 feet, etc. Similar changes in 2024 IBC.	H	M	Further research on origin and impact of changes needed.	*				
8-24	8	Table 804.5.1.1(2)	Table 804.4.1.1(1)	Table 805.3.1.1(2)	L2 Means of Egress, Stories with One Exit or Access to One Exit for Other Occupancies		Change in 2024 adds occupiable roofs, changes 1st occ load to 49, adds B and F to allowance for 100 feet exit access travel distance.	H	M	Further research on origin and impact of changes needed.	*				
8-25	8	804.5.1.2-804.10.2	804.4.1.2 - 804.12.2	805.3.1.2-805.11.2	L2 Means of Egress, Multiple Sections		2024, renumbered, including subsections.	N	N		A				
8-26	8	804.6.1.2	804.5.1.2	805.4.1.2	L2 Means of Egress, Egress Doorways, Group I-2		Change in 2021. I-2 Cond. 2 altered care suites comply with IBC 407.4.4-407.4.6.2.	H	M		A				
8-27	8	804.6.4	804.5.4	805.4.4	L2 Means of Egress, Egress Doorways, Panic Hardware		Change in 2021. Adds compliance with IBC 1010.2.	H	M		A				
8-28	8	804.7.3	804.6.3	805.5.3	L2 Means of Egress, Openings in Corridor Walls, Other Corridor Openings		Change in 2021. Adds option to protect openings per IBC 716.	H	M		A				
8-29	8	804.8	804.7	805.6	L2 Means of Egress, Dead-End Corridors		Change in 2021. Adds I-2s with max 30 feet and adds I-2s to exceptions.	H	M		A				
8-30	8	804.14.2		805.11.2	L2 Means of Egress, Guards, Design		Change in 2024. <i>Exception: In Group I-1 and I-2 facilities, required guards enclosing the occupiable roof areas shall be permitted to be greater than 48 inches (1219 mm) above the surface of the occupiable roof where the occupants, because of clinical needs, require restraint or containment as part of a function of a psychiatric or cognitive treatment area.</i>	H	L		A				
8-31	8			1311.0806.2	L2 Structural, Existing Structural Elements Carrying Gravity Loads	Y	MN amendment. Priority to Structural TAG.				*				
8-32	8			1311.0806.3	L2 Structural, Existing Structural Elements Resisting Lateral Loads	Y	MN amendment. Priority to Structural TAG.				*				
8-33	8	805.3		806.3	L2 Structural, Existing Structural Elements Resisting Lateral Loads		Changes in 2024. Priority to Structural TAG.				*				
8-34	8	805.4		806.4	L2 Structural, Voluntary Lateral Force-Resisting System Alterations		Changes in 2024. Priority to Structural TAG.				*				

8-35	8	806.3	806.3		L2 Electrical, Health Care Facilities		New in 2021, I-2s, ambulatory care, outpatient clinics additions to electrical system install and equipment per NFPA 99.	H	L	CCLD Electrical Unit is aware of change.	A				
8-36	8	808.1	808.1		L2 Plumbing, Health Care Facilities		New in 2021, I-2s, ambulatory care, outpatient clinics additions to med gas system install and equipment per NFPA 99.	H	L		A				