

[Link to 2024 IEBC \(changes in blue\)](#)

[Link to 2021 IEBC \(changes in blue\)](#)

Meeting #5

To Be Completed by TAG Leads											TAG Meeting Results				
Item Number	2024 IEBC Chapter	2024 IEBC Code Section	2021 IEBC Code Section	2020 MN Code Section	Code Section Heading/Topic	MN Amendment?	Description of change(s) to code language	Safety/Health Value	Cost Impact	Staff Comment	Staff Recommendation	TAG Recommendation	TAG Group Consensus	Stakeholder Consensus	Comments
								N - None, L - Low, M-Med, H-High					Y or N	Y or N	
<b>1311.0010 Adoption and 1311.0020 References to other Codes</b>															
0-1				1300.0040 Subp. 2	Compliance	Y		N	N	Coordinate with 1300 TAG	AM	NA	Y		No recommendation needed. 1300 TAG will address.
0-1	0			1311.0010	General & Mandatory Chapters	Y	Sections contain references to dated editions and code sections which need to be revised for current MSBC	N	N	Revise amendment.	AM*	AM	Y		Revise amend. to correct dates.
0-1.2				1311.0010 Subp. 3 Item D	Construction Safeguards	Y	Using IBC Ch 33.			Coordinate with 1305 TAG.	AM*	AM	Y		Coordinate with 1305 TAG and a CCP related to this section.
0-2	0			1311.0020	References to Other Codes	Y	Modifies & establishes references to other codes.	N	N	Carry over amendment.	AM	AM	Y		Carry over amendment.
0-3				CCP-EB-11	References to Other Codes - Fire Code		Proposes reference to IFC mean to MN Fire Code.								Review at June 11 meeting.
0-4				CCP-EB-10	References to Other Codes - Residential Code		Proposes to make Conservation Code applicable to IRC/1309 buildings. Revision to 1300.0020 Subp. 9.								Review at June 11 meeting.
<b>Chapter 2 Definitions</b>															
2-1	2	202		1305.0202	Ambulatory Care Facility	Y	Definition brought into 2024 IEBC from IBC. MN amended the IBC definition of ACF in MR 1305.	N	N	Ensure definition matches 1305 for the 2026 cycle.	AM*	A	Y		Coordinate with 1300 and 1305 TAGs. Revisit.
2-2	2	202	202	1311.0202	Approved	Y	MN amendment more specific than model code	N	N	Carry over amendment	AM	AM	Y		
2-3	2	202			Approved Agency	N	New definition in 2024	N	N		A	A	Y		
2-4	2	202	202		Change of Occupancy	N	New definition in 2021; Revised definition 2024	N	N	Support - Coordinate with 1305	A*	A	Y		Coordinate with 1305 TAG. New definition qualifies a "change of occupancy" to when code requires a <u>greater degree of safety</u> .
2-5	2	202	202		Change of Use	N	New definition 2021	N	N	Support - Coordinate with 1305	A	A	Y		Discussion. Support.
2-6	2	202		1311.0202	Code	Y	Definition not present in model code	N	N	Carry over amendment	AM	A	Y		Carry over amendment
2-7	2	202	202		Code Official	Y	MN amendment differs from model code	N	N	Carry over amendment	AM	A	Y		Carry over amendment

Recommendations A - Accept Model Code AM - Amend Model Code D - Delete MN Amendment R - Reject

2-8	2	202	202		Dangerous	N	Revised 2021 - Expands loading conditions; Added 'aftershock' 2024.	L	N	Support - Coordinate with structural.	A	A	Y		(Structural TAG recommends accepting.)
2-9	2	202			Disproportionate Earthquake Damage	N	Revised definition 2024	N	N	Seismic and earthquake provisions made non-applicable elsewhere in MN code.	A	A	Y		Seismic and earthquake provisions made non-applicable elsewhere in MN code.
2-10	2	202	202		Emergency Escape and Rescue Opening	N	New in 2021 IEBC. Same as IBC.	N	N	Support - coordinate with 1305.	A*	A	Y		Staff coordination with 1305 and 1309.
2-11	2	202	202	1311.0202	Existing Building	Y	MN amendment more specific than model code.	N	N	Carry over amendment	AM	AM	Y		Carry over amendment.
2-12	2	202	202		Exterior Wall Covering; Exterior Wall Envelope	N	New in 2021 IEBC. Same as IBC.	N	N		A	A	Y		
2-13	2	202	202	1311.0202	Historic Building	Y	MN amendment references definition in 1300.0700 Subp. 12a	N	N	Carry over amendment	AM	AM	Y		Carry over amendment.
2-14	2	202			Listed	N	New in 2024 IEBC. Same as IBC.	N	N		A	A	Y		
2-15	2	202			Lowest Floor	N	New in 2024 IEBC. Same as IBC.	N	N	Coordinate with 1305.	A	A	Y		(1305 TAG recommends accept 2024 IBC definition.)
2-16	2	202			Occupiable Roof	N	New in 2024 IEBC, same as new definition in 2024 IBC.	N	N	Ensure definition matches 1305 for 2026 cycle.	A	A	Y		(1305 TAG recommends accept 2024 IBC definition.)
2-17	2	202			Peer Review	N	New in 2024 IEBC, same as new definition in 2024 IBC. Pertains to Storm Shelter design and construction.	N	N	Ensure definition matches 1305 for the 2026 cycle.	A	A	Y		Some discussion. (1305 TAG recommends accept 2024 IBC definition.)
2-18	2	202			Photovoltaic Panel System	N	New in 2024 IEBC. Same as IBC.			Coordinate with 1305.	A	A	Y		
2-19	2	202		1311.0202	Repair	Y	MN amendment differs from model code.	N	N		AM	AM	Y		
2-20	2	202			Storm Shelter	N	New in 2024 IEBC. Same as IBC.	N	N		A	A	Y		
2-21	2	202		1311.0202	Substantial Damage	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM	AM	Y		Discussion. JB to research. Amendment removes 'floodplain' because flood regs are in MR 1335, not 1311. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.
2-22	2	202		1311.0202	Substantial Improvement	Y	MN amendment differs from model code.	N	N	Carry over amendment-coordinate with Structural.	AM	AM	Y		Discussion. JB to research. Amendment removes 'floodplain' because flood regs are in MR 1335, not 1311. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.

2-23	2	202			Substantial Structural Damage	N	Small change to language in 2024 - Only the last sentence added to clarify work done to implement repairs shall not be considered damage that reduces structural capacity.	N	N	Coordinate with 1305 & Structural TAG. Structural TAG recommends accept change.	A	A	Y		Discussion. Tabled. JB to research. (Structural TAG defers to 1311 and 1335.) Consensus 4/30.
2-24	2	202	202		Technically Infeasible	Y	Definition not present in published 1311 MCCEB. See definitions for Technically Infeasible, Accessibility and Technically Infeasible, Stair Construction	N	N	Addressed in amendments Technically Infeasible Accessibility and Technically Infeasible Stair Construction.	AM	AM	Y		Relates to Accessibility, which is purview of 1341 TAG. Replaced with amendment only adding "Accessibility" to defined term to distinguish from "Technically Infeasible, Stair Construction". No change in application.
2-25	2			1311.0202	Technically Infeasible, Accessibility	Y	Definition not present in model code. Pertains to accessibility in existing buildings.	N	N	Check with 1341 TAG chair and rules coordinator.	AM	AM	Y		Relates to Accessibility, which is purview of 1341 TAG. Amendment only adds "Accessibility" to defined term to distinguish from "Technically Infeasible, Stairways". No change in application.
2-26	2			1311.0202	Technically Infeasible, Stair Construction	Y	Definition not present in model code.	N	N	Carry over amendment.	AM	AM	Y		Discussion. Some interest in why only limited to stair. Amendment <i>expands</i> availability of technically infeasible beyond the model code language. Revisit. 4/30-MB to research amendment. 5/14-carry forward.
<b>Chapter 3 Provisions for All Compliance Methods</b>															
3-1	3	301.1	301.1	301.1	Applicability/General	N	In 2021, new Applicability section (moved from 302) replaces General in 2018	N	N	Coordinate added sections from CCPs. Looks like a good change coordinating sections 302-309 (and then some) applicable to all methods (formerly section 302.1).	AM (if CCP's)*	A or AM if needed	Y		Will only need amendment if CCP's extend numbered sections.
3-2	3	301.1.1	301.1.1		Bleachers		Added in 2021 - Refers bleachers to ICC 300.	H	L	Bleacher code ICC 300 will need to be added to 1311.0020 or state adoption and amendments referenced here.	A	A	Y		

3-3	3	301.3	301.3	301.3	Alteration, Addition, or Change of Occupancy		Revised in 2021 - Reorganized and removes accessibility.	N	N	Discuss Ex. 1 and 2, coordinate 3 with structural.	A*	A	Y		Discussion. No substantive change in application except that Ex. 1 exempts accessibility, which is the purview of 1341 TAG. Coordinate with Structural.
3-4	3	301.3.1	301.3.1	1311.0301.3.1	Prescriptive Compliance Methods	Y	Model codes 2021 and 2024 reference IFC. MN Amendment requires compliance with Ch 5 Prescriptive Compliance.	N	N	Carry over amendment.	AM	AM	Y		Consensus not unanimous. Fire Code still applies, administered by Dept. of Public Safety, not CCLD. Table 4/30. 5/14 carry forward.
3-5	3			1311.0301.5	Accessibility in Existing Buildings	Y	Section added. Compliance for accessibility sent to 1341	N	N	Carry over amendment.	AM*	A	Y		Carry over amendment - sent accessibility to 1341.
3-5.1	3	302.2			Additional Codes		List of other codes applicable to existing buildings.	N	N	Review for consistency with MN adopted codes.	A	A	Y		
3-6	3	302.2.1	302.2.1		Health Care Facilities Applicability		New subsection. Added in 2021, adds compliance with NFPA 99 Health Care Facilities Code for health care occupancies	N	N	Discuss.	A	A	y		Discussion. Added in 2021, no change in 2024. Currently NFPA 99 referenced in 1311 and 1305.
3-7	3			1311.0302.3.1	Window Cleaning Anchors	Y	Amendment adds provision for Window cleaning anchors comply with 1305. This will need to be renumbered if carried over (to 302.2.2)	N	N	Carry over amendment.	AM	AM	Y		Carry over amendment.
3-8	3	302.3	302.3		Existing materials		In 2021 changed 'building official' to 'code' official. Also renumbered - was 302.5.	N	N	Discuss. Our current amendment of CODE OFFICIAL in 202 already refers to 1300.0070, subpart 5.	A	A	Y		Discussion. Our current amendment of CODE OFFICIAL in 202 already refers to 1300.0070, subpart 5.
3-9	3	303	303.1; 303.1.1		Storm Shelters (Moved) General; Construction		2021 relocates Storm Shelters from Chapter 11 (Additions) to Chapter 3 (All Compliance Methods). Revised language.	N	N	Discuss and coordinate with 1305 Ch 4. Amendment needed to specify counties where applicable. Add Mower County to list.	AM*	AM	Y		Discuss and coordinate with 1305 Ch 4. Amendment needed to specify counties where applicable. Add Mower County to list.
3-10	3	304			Structural/Seismic		Revisions to seismic requirements only.	N	N	Coordinate with Structural TAG.	A	A	Y		(Structural TAG recommending acceptance of seismic references throughout model IBC and ICEB because MR 1305.0011 Subp. 4 and 1311.0010 Subp. 4 deletes any references to earthquake or seismic provisions.)

3-10.1	3	305			In-Situ Load Tests		Renumbered in 2021 from 304 to 305.				A	A	Y		
3-11	3	306		1311.0305 (multiple sections)	Accessibility in Existing Buildings	Y	Changes made in both code cycles. Needs to be renumbered to 1311.0306.	N	N	Send to 1341 TAG.	AM*	A	Y		All accessibility to 1341 TAG.
3-11.1					CCP-EB-1 Sounders (Smoke Alarms)		For all compliance methods, smoke alarms and fire alarm annunciators in dwelling.sleeping units per fire code, except repair and Level 1 alterations. Revision to 307.1, adds subsections.			If accepted, need to change Section title to encompass fire detection and alarms.					Table until June 11 meeting to review CCPs.
3-12	3	307.1	307.1				Moved in 2021 from individual compliance methods to Ch 3 and is applicable to all compliance methods except for the exception. Consider deleting the exception to align with 1309.	H	N	See proposed amendment CCP-EB-1. Also, apply the current amendment to 503.14 here. Consider amendment to delete the exception. (coordinate with 1305 and 1309 TAGs)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-12.1	3			1311.0503.14		y	Smoke alarm code sections from other chapters moved to 307. Carry amendment to new smoke alarm location. Renumber to 1311.0307. Amendment points to 1305.	No change.	No change.	(coordinate with 1305 and 1309 TAG's)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-13	3	307	307	1311.0307.1, 1311.307.1.1, 1311.307.1.2	Smoke Alarms	Y	Conforms req. for annunciators in dwelling units with Fire Code.	H	L	See CCP-EB-1. Discuss at 6/11 Meeting.	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-14	3	308	308.1	1311.0503.15	Carbon Monoxide Detection (Moved)	y	Section relocated here in 2021, revision for I-2s in 2024 in exception #4. Added 'E's' in 2021. Removed specific occupancies in the 2024 and changed wording to existing buildings.	H	N	The amendment to 503.15 should be applied here. Propose amending reference to IBC instead of IFC/IRC and deleting exception #3 (coordinate with 1305 and 1309 TAG's)	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-14.1	3			1311.0503.15	Carbon Monoxide Alarms	Y	Carry amendment from Ch 5 to new location in Ch 3.	H	N	(coordinate with 1305 and 1309 TAGs).	AM*				Table until June 11 meeting when proponent for related CCPs present at meeting.
3-15	3	309	309		Add & Replace Ext Wall Covering & Envelope	N	Section added in 2021, revision for high rises in 2024.	H	M		A	A	Y		Public member concerned with scope of requirements. MB to research reason for addition in model code.

3-15.1					CCP-EB-6 Elevator Hoistway Opening Protection		When add, alter, change occ., elev. hoistway opening protection required, except historical, repair, or Level 1 alterations. If accepted, would be 1311.0310.								Table until June 11 meeting to review CCPs.
3-16	3				CCP-EB-2 Energy Conservation		If accepted, would be 1311.0311.	L	M	Currently, all references in IEBC to 1322 and 1323 per 1311.0020.					Table until June 11 meeting to review CCPs.
3-17	3				CCP-EB-3 Energy Code for Existing Buildings		If accepted, would be 1311.0311	L	M	Currently, all references in IEBC to 1322 and 1323 per 1311.0020.					Table until June 11 meeting to review CCPs.
3-18	3				CCP-EB-4 Electric Vehicle Charging Stations	Y	Adds scoping for EV charging stations. If accepted, would be MR 1311.0312.	L	M	Support, but need cost benefit analysis information.					Table until June 11 meeting to review CCPs.
<b>Chapter 4 Repairs</b>															
4-1	4		401.1.1		Bleachers, etc.		New in 2021 - Repairs shall comply with ICC 300.	H	L		A	A	Y		
4-2	4	401.2			Compliance		2024 adds language for nondamaged components incidental to repair.	N	L		A	A	Y		
4-3	4	405	405	405	Structural	Y	Minor change 2021. More changes 2024.	H	M	Send to Structural TAG.	A*	A	Y		Coordinate with Structural TAG.
4-4	4			1311.0405.2.4	Substantial Structural Damage to Gravity Load-Carrying Components	Y	Amendment requires demonstration that components have capacity to carry design loads of rehab design. Current amendment and also new language in model code.	H	M	Send to Structural TAG.	AM*	AM	Y		Discussion. Public member concerned with scope of requirements. Has been in code since 2006. Priority for recommendation to Structural TAG.
4-5	4	406.1	406.1		General Electrical		Changes "material" to "general". Requires repairs to comply with NFPA 70. Previously, allowed to be replaced with like material.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-6	4	406.1.1	406.1.1		Reconditioned Electrical Equipment		Eliminates "Receptacles" section, replaces with requirement for reconditioned equipment to comply with NFPA 70 or NFPA 99.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-7	4	406.1.2	406.1.2		Plug Fuses - Deleted		Eliminated in 2024.	N	N	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-8	4	406.1.2	406.1.4		Health Care Facilities (Electrical)		Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics repairs shall comply with NFPA 99.	H	M	Obtain input from Electrical Unit.	A	A	Y		Electrical unit aware of model code language.
4-9	4	408.3	408.3		Health Care Facilities (Plumbing)		Added in 2021, renumbered in 2024. Group I-2, ambulatory care facilities and outpatient clinics med gas system repairs shall comply with NFPA 99.	H	M		A	A	Y		

Chapter 5 Prescriptive Compliance Method														
5-1	5	501.3	501.3		Health Care Facilities (Prescriptive Compliance)		Added in 2021, Group I-2, ambulatory care facilities and outpatient clinics alterations and additions electrical or med gas systems shall comply with NFPA 99.	H	L		A	A	Y	
5-2	5	502.1	502.1		General (Additions)		Revised in 2024 - limits some structural compliance requirements, specifies addition of occupiable roof shall comply with IBC (with exception).	M		Coordinate with Structural TAG and obtain input on cost.	*	A	Y	Coordinate with Structural.
5-3	5	502.1.1			Risk Category Assignment (Additions)		New in 2024.			Coordinate with Structural; TAG and obtain input on cost.	*	A	Y	Coordinate with Structural.
5-4	5	502.1.2			Creation or Extension of Nonconformity (Additions)		New in 2024 (with exception).			Coordinate with Structural TAG and obtain input on cost.	*	A	Y	Coordinate with Structural.
5-5	5		502.2		Disproportionate Earthquake Damage (Additions) - Deleted		Eliminated in 2024.	N	N		A	A	Y	
5-6	5	502.2		502.3	Flood Hazard Areas (Additions)		Renumbered and revised in 2024.	M	N	Coordinate with MR 1335 Floodproofing Regs.	A	A	Y	
5-7	5	502.3	502.4	1311.502.4	Existing Structural Elements Carrying Gravity Loads (Additions)	y	Renumbered in 2024.			Send to Structural TAG.	*	AM	Y	
5-8	5	502.4	502.5	1311.0502.5	Existing Structural Elements Carrying Lateral Loads (Additions)	Y	Renumbered and revised in 2024.			Send to Structural TAG.	*	AM	Y	
5-9	5	502.5			Smoke Barriers in Group I-1, Cond. 2 (Additions)		New in 2024. Addresses smoke barriers in additions to I-1 Cond. 2.	H	L		A	A	Y	
5-10	5		502.6	1311.0502.6	Smoke Alarms in Existing Portions of a Building (Additions) - Relocated	Y	Relocated in 2021. Now addressed in 307.1. See also CCP-EB-1.	H	L	Amendment not needed here - address in 307.1.	AM*	AM	Y	Amendment to be in Ch. 3.
5-11	5	502.6	502.6		Enhanced Classroom Acoustics (Additions)		New in 2021. Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.	H	M	Coordinate with 1341 TAG.	A	A	Y	Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.
5-12	5	503.1	503.1	1311.0503.1	General (Alterations)	Y	Reworded in 2021, structural revision in 2024. MN amendment modifies exceptions.			Coordinate with Structural TAG. Review language.	AM*	A	Y	
5-13	5	503.3		1311.0503.3	Existing Structural Elements Carrying Gravity Load (Alterations)	Y	No changes in 2021 or 2024.			Send to Structural TAG.	AM*			Send to Structural TAG.

5-14	5	503.4	503.4	1311.0503.4	Existing Structural Elements Carrying Lateral Loads (Alterations)	Y	Exceptions 1 revised & 2 added in 2021. Further revision of Exception 1, and addition of Exception 3 in 2024 related to seismic. MN amendment rewords Exception 1.			Send to Structural TAG.	AM*				Send to Structural TAG.
5-15	5	503.5	503.5	503.5	Seismic Design Category F		Seismic revised in 2024. Proposed CC-P to replace with Reroofing.			See proposed amendment CCP-EB-5 replacing this section.					Table until June 11 meeting when proponent for related CCPs present at meeting.
5-16	5				CCP-EB-5 Reroofing Prescriptive (Alterations)		Proposal deletes seismic provision, replaces with direction to comply with 1305 for reroofing. Would be 1311.0503.5			See CCP-EB-5.					Table until June 11 meeting to review CCPs.
5-17	5	503.6, 503.7, 503.8, 503.9, 503.10, 503.11, 503.12, 503.13			Bracing and Anchorage for Parapets, Bracing and Anchorage for Masonry Walls, Substantial Structural Alteration, Roof Diaphragms Resisting Wind Loads, Voluntary Lateral-Force Resisting Systems (Alterations)		Several 2024 changes in these sections, some referencing IEBC Ch 3. Roof Diaphragm revised 2021 and 2024.			Send to Structural TAG.	*				Send to Structural TAG.
5-18	5	503.14	503.14		Smoke Compartments (Alterations)		Relocated 2021. Was under Refuge Areas. Addresses smoke compartments in I-2s for alterations. Language changed in 2021. No changes in 2024.	L	L		A	A	Y		
5-19	5			1311.0503.14	Smoke Alarms in Existing Portions of a Building (Alterations) - Relocated to 307.1	Y	Smoke alarms relocated to 307.1 in 2021. See also CCP-EB-1. One exception added.	H	L	Current amendment to 503.14 not needed here 307.1 needs this amendment.	AM				Table until June 11 meeting when proponent for related CCPs present at meeting.
5-19	5			1311.0503.15	Carbon Monoxide Alarms	Y	CO alarms relocated to 308 in 2021. Two exceptions added.	H	L	Current amendment to 503.15 not needed here. 308 needs amendment.	AM				Table until June 11 meeting when proponent for related CCPs present at meeting.
5-20	5	503.15	503.15		Refuge Areas		Revised in 2021. Minor change in 2024.	H	L	From 2018: 503.16.1 Smoke Compartments now in 503.14; 503.16.2 Ambulatory Care now in 503.17; 503.16.3 Horizontal Exits address here in 503.15.	A	A	y		
5-21	5	503.16, 503.16.1			Conditions for Group I-1 Occupancies; Smoke Barriers in Group I-1, Cond. 2		New in 2024.	H	M		A	A	Y		



5-22	5	503.17			Ambulatory Care Facilities		New language in 2024. Was under Refuge Areas.	H	M		A	A	Y		
5-23	5	503.18	503.16		Enhanced Classroom Acoustics (Alterations)		New in 2021. Renumbered in 2024	H	M	Coordinate with 1341.	A	A	Y		Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.
5-24	5	503.19	503.17		Locking Arrangements in Educational Occupancies		New in 2021. Renumbered in 2024. Reference to IBC numbering is incorrect in model code. Should be 1010.2.7.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A	A	Y		
5-25	5	503.20	503.18		Two-Way Communication Systems		New in 2021. Renumbered in 2024.	H	M		A	A	Y		
5-25.2	5	504.4		1311.504.4	Fire Escapes, Dimensions	Y		M	L	Carry over.	AM	AM	Y		
5-26	5	505.1	505.1	505.1	Replacement Windows		Changed "glass" to "windows" in 2021. No change in 2024.	L	L		A				Discussion, Window manf.'s instructions don't cover existing buildings. Mike to research. Revisit. CCP coming from IP. Table 5/14
5-27	5	505.2	505.2	505.2	Window Fall Prevention on Replacement Windows		Sub-section revised in 2021. Renamed in 2024 from "Window Opening Control Devices on Replacement Windows" to new heading.	H	L		A	A	Y		
5-28	5	505.3; 505.3.1	505.3; 503.3.1	505.3	Replacement Window Emergency Escape and Rescue Openings		Some changes in 2021, including separating Control Devices to a sub-section. Only revised IRC citation in 2024.	H	L		A	A	Y		
5-29	5			1311.0505.3.1	Licensed Facilities	Y	Addresses requirements for foster care, day care licensed or registered by the State.	H	L	Insert current MCCEB amendment 505.3.1 Licensed facilities into the 2024 IEBC at 505.4 and renumber 505.4 Bars, grilles, covers or screens to 505.5.	AM*	AM	Y		
5-30	5	505.4	505.4		Bars, Grilles, Covers or Screens		Renamed in 2021 to "Bars, Grilles, Covers or Screens". Was "Emergency Escape and Rescue Openings"	H	L	Insert current MCCEB amendment 505.3.1 Licensed facilities into the 2024 IEBC at 505.4 and renumber 505.4 Bars, grilles, covers or screens to 505.5.	A*	A	Y		

5-30.1	5			1311.0505.4	Windows and Emergency Escape Openings	Y	Amendment removes reference to Smoke Alarms in model code. Smoke Alarms are addressed elsewhere.	H	L	Delete.	D	D	Y		Delete amendment. Accept model code.
5-31	5	506.1	506.1	1311.0506.1	Compliance	Y	MN amendment references the Life-Safety and Fire Risk Table 506.1.	H	L	Carry over.	AM	AM	Y		
5-31.1	5			CCP-EB-8	Table - Prescriptive Life Safety & Fire Risk		Proposed revision to MR Table 506.1	H	L	Review 2018 SONAR for the original amendment.					Table until June 11 meeting to review CCPs.
5-32	5			1311.0506.1.2	Small Assembly Spaces	Y	Language similar to IBC Ch 3.	M	L	Carry over.	AM	AM	Y		MB to research. Consensus without majority.
5-33	5	506.4	506.4		Existing Emergency Escape and Rescue Openings (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Coordinate with 1305 and 7511.	AM*				Carried forward to future meeting.
5-34	5	506.5.3	506.5.3; 506.5.4	506.4.3; 506.4.4	Seismic Loads (seismic force-resisting system); Access to Risk Category IV		Changes in 2021 and 2024			Priority Structural	A*				Coordinate with Structural for Risk Categories.
5-35	5	506.6	506.6		Enhanced Classroom Acoustics (Change of Occupancy)		Added to 506 Change of Occupancy in 2021.	H	M	Coordinate with 1341.	A	A	Y		Requires enhanced acoustics in additions with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.
<b>Chapter 6 Classification of Work (Work Area Compliance)</b>															
6-1	6	601.1			General Scope		Change in 2024. Removes moved buildings from scope for Classification of Work method.	L	L		A	A	Y		
6-2	6	603.1	603.1		Scope		Change in 2021. Adds qualifier that Level 2 Alterations are work area less than 50% of building area where within the scope of work described. Exception clarifies exempt items.	L	L		A	A	Y		
<b>Chapter 7 Alterations - Level 1</b>															
7-1	7	701.3			Flood Hazard Areas Level 1 Alterations		Change in numbering for work in flood hazard area. MR 1311.0010 Subp. 3, C already sends this to MR Chapter 1335	L	L		A	A	Y		
7-2	7	702.4	702.4		Window Fall Prevention		2021 changes "bottom of sill" to "bottom of the clear opening". 2024 Changes title of section and adds "or other window fall prevention devices".	H	L	Confirm consistent with 1305 and 1309.	A	A	Y		
7-3	7	702.5	702.5		Replacement Window for Emergency Escape and Rescue Openings		2021 added "for" in section title. Renumbered reference to IRC and IBC sections. Sends replacement windows for change of occupancy to IEBC Ch 10.	H	L		AM				Tabled 5/14 for comparison/coordination with 7511 and 1305 TAGs and DoH reqs.

7-4	7			1311.0702.5	Replacement Window Emergency Escape and Rescue Openings; Licensed Facilities	Y	Amends and adds subsection 702.5.1. Removes reference to IRC buildings; combines window opening control devices (found in subsection 702.5.1 in model codes) to main section. Added subsection 702.5.1 addresses foster care or day care licensed or registered by state of MN.	H	L	Insert current MCCEB amendment 702.5.1 Licensed facilities into the 2024 IEBC at 702.6 and renumber 702.6 Bars, grilles, covers or screens to 702.7. Also renumber Sections 702.7 Materials and methods and 702.7.1 International Fuel Gas Code to 702.8 and 702.8.1. Carry over first part of amendment, second part not needed.	AM*				Tabled 5/14 for comparison/coordination with 7511 and 1305 TAGs and DoH reqs.
7-5	7	702.5.1	702.5.1		Control Devices (Replacement EEROs)		New sub-section for control devices for replacement EEROs added in 2021.	H	L		A				Tabled 5/14 for comparison/coordination with 7511 and 1305 TAGs and DoH reqs.
7-6	7	702.6	702.6		Bars, Grilles, Covers or Screens		New section in 2021. Allows if meeting clear opening for code under which building was constructed.	H	L	Insert current MCCEB amendment 702.5.1 Licensed facilities into the 2024 IEBC at 702.6 and renumber 702.6 Bars, grilles, covers or screens to 702.7. Also renumber Sections 702.7 Materials and methods and 702.7.1 International Fuel Gas Code to 702.8 and 702.8.1.	A	A	Y		
7-7	7	704.1.1	704.1.1		Projections in Nursing Home Corridors (Means of Egress)		New in 2021.	H	L		A	A	Y		
7-8	7	704.2	704.2		Casework (MOE)		New in 2021	H	L		A	A	Y		
7-9	7	704.3	704.3		Locking Arrangements in Educational Occupancies (MOE)		New in 2021. Includes E, B ed occupancies, and I-4.	H	M	Watch for errata. Reference to 1010.2.8 was renumbered to 1010.2.7.	A	A	Y		
7-10	7			CCP-EB-7	Level 1 - General - Reroofing		Revises Exception 1, deletes Exception 2.			See CCP-EB-7					Table until June 11 meeting to review CCPs.
7-11	7	705.1			General - Reroofing		For Ex. 1 and 2, adds requirement to comply with IBC Snow and Rain Loads			Send to Structural TAG.	*				

7-12	7		705.2		Structural and Construction Loads		Moved to Chapter 15 (Construction Safeguards IBC 33 3301.3 Roof Loads).			Send to Structural TAG.	*				
7-13	7	705.2			Roof Replacement		Changed in 2024. Now 3 exceptions to removal of all existing layers of coverings down to deck.	L	L		A	A	Y		
7-14	7	705.3			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024.	L	L		A	A	Y		
7-15	7	705.3.1			Roof Recovering Over Wood Shingles or Shakes		Renumbered in 2024; Renamed in 2024; Added "panel products" to gypsum in 2024.	L	L		A	A	Y		
7-15.1	7	705.4			Reinstallation of Materials					Consider mirror 1305/ IBC 1512.4 (Currently 1305.1511.5).	AM				
7-16	7			1311.0706.2	Addition or Replacement of Roofing or Replacement of Equipment	Y				Send to Structural TAG.	*				
7-17	7	706.3.1			Bracing for Unreinforced Masonry Bearing Wall Parapets		Change in 2024.			Send to Structural TAG.	*				
7-18	7	706.3.2	706.3.2		Roof Diaphragms Resisting Wind Loads in High-Wing Regions		Change in 2021 and again in 2024.			Send to Structural TAG.	*				
7-19	7	707	707		Health Care Facilities		Added in 2021. I-2s, ACFs, outpatient clinics altered electrical systems comply with NFPA 99.	H	L	Electrical unit is aware of change.	A	A	Y		
7-20	7	708		1311.0707	Energy Conservation	Y	Sends Ch 7 Energy to MN Energy Code 1322 and 1323	M	M		AM	AM	Y		
<b>Chapter 8 Alterations - Level 2</b>															
8-1	8			1311.0801.1	Work Area Method Level 2 General, Scope	Y	MN amendment deletes exception for reconfigure for accessibility.	N	N		AM*	AM	Y		
8-2	8	801.3	801.3		L2 System Installations		New in 2021. Requirements related to work area are not applicable where the Level 2 alterations are limited solely to mech, elec, fire prot., haz mat abatement, windows, hardware, op. controls, elec. outlets, signs, alterations primarily for accessibility.	N	L		A	A	Y		Table 5/14. MB to research purpose. 1341 TAG chairs have no issue with this. Similar to 1341/MAC 306.7.
8-2.1	8	802.3	802.3	802.3	L2 Smoke Compartments		Change in 2021. Changes "patients" to "care recipients."	M	L		A	A	Y		
8-3	8	802.4	802.4		L2 Interior Finish		Change in 2021. Adds 'trim', clarifies exception, adds testing.	N	N		A	A	Y		
8-4	8	802.4.1	802.4.1		L2 Supplemental Interior Finish Requirements		Change in 2021. Adds 'trim'.	N	N		A	A	Y		
8-5	8	803.2.2	803.2.2		L2 Automatic Sprinkler Systems, Specific Occupancy Groups		Change in 2021. Breaks out I occupancies.	N	N		A	A	Y		

8-6	8	803.2.2 Ex.			L2 Automatic Sprinkler Systems, Specific Occupancy Groups		Change in 2024. For specific occupancy groups, revises (clarifies?) the exception for no water available-then smoke detection req.	H	N		A	A	Y		
8-7	8	803.2.3	803.2.3		L2 Automatic Sprinkler Systems, Group I-2		Change in 2021. Sprinkler reqs for I-2s.	H	M		A	A	Y		
8-8	8	803.2.5	803.2.5		L2 Automatic Sprinkler Systems, Other Required Automatic Sprinkler Systems		New in 2021. Requirements related to work area with shared exits or corridors by more than one tenant or occ load greater than 30, work area requires sprinklers.	H	M		A	A	Y		
8-9	8	803.2.5			L2 Automatic Sprinkler Systems, Other Required Automatic Sprinkler Systems		Change in 2024. For other buildings and areas listed in IBC T 903.2.11.6, revises (clarifies?) the condition where sprinklers req.	H	N		A	A	Y		
8-10	8	803.2.6	803.2.6		L2 Automatic Sprinkler System Supervision		Change in 2021. Clarifies Ex. 1.	N	N		A	A	Y		
8-11	8	803.2.6			L2 Automatic Sprinkler System Supervision		Change in 2024. References IBC 903.4 for sprinkler supervision.	H	L		A	A	Y		
8-12	8	803.4			L2 Fire Alarm and Detection		Changes in 2024. Reorganizes, specifies reference to IFC CH 11 for several occupancies.	H	N		A	A	Y		
8-13	8	803.4.1.1			L2 Fire Alarm and Detection, Group E		Change in 2024. Specifies reverence to IFC Ch 11.	H	N		A	A	Y		
8-14	8	803.4.1.2	803.4.1.2		L2 Fire Alarm and Detection, Group I-1		Change in 2021. Removed "residential care/ assisted living".	H	N		A	A	Y		
8-15	8	803.4.1.3	803.4.1.3		L2 Fire Alarm and Detection, Group I-2		Change in 2021. Specifies reference to IFC Ch 11.	H	N		A	A	Y		
8-16	8	803.4.1.5			L2 Fire Alarm and Detection, Group R-1		Change in 2024. Specifies reverence to IFC Ch 11.	H	N		A	A	Y		
8-17	8	803.4.3			L2 Fire Alarm and Detection, Installation		Change in 2024 reorganization of section. This basic language was in 803.4, requires compliance with IBC 907 and NFPA 72.	H	N		A	A	Y		
8-18	8	804.3	804.3	805	L2 Means of Egress, Group I-2		New section 2021. In I-2s, where corridors are used for movement of beds, ramps and corridors to be 48" or more. (All of Means of Egress renumbered in 2021 from 805 to 804.)	H	M		A	A	Y		
8-19	8	804.2		1311.0805.2	L2 Means of Egress, General	Y	MN amendment. (Section renumbered to 804.2)	N	N		AM	AM	Y		Amendment will be to 804.2 in 2024.
8-20	8	804.4	804.11	805.10	L2 Refuge Areas		Revised in 2021. Moved in 2024 to 804.4.	H	L		A	A	Y		
8-21	8	804.5; 804.5.1			L2 Means of Egress, Refuge Areas; Number of Exits		Renumbered in 2024. Adds "or access to exits" and changes "occupied roof to "occupiable roof".	H	N		A	A	Y		

8-22	8	804.5.1.1	804.4.1.1	805.3.1.1	L2 Means of Egress, Single-Exit Buildings		2021 changes "non-sprinklered" to "without an approved automatic sprinkler system". 2024 changes "occupied roof" to "occupiable roof".	H	M	Further research on origin and impact of changes needed.	*				Further research needed.
8-23	8	Table 804.5.1.1(1)	Table 804.4.1.1(1)	Table 805.3.1.1(1)	L2 Means of Egress, Stories with One Exit or Access to One Exit for R-2 Occupancies		2021 changes footnote a - "non-sprinklered" to "without an approved automatic sprinkler system". In 2024, increases to 3rd story, 125 feet, etc. Similar changes in 2024 IBC.	H	M	Further research on origin and impact of changes needed.	*				Further research needed.
8-24	8	Table 804.5.1.1(2)	Table 804.4.1.1(1)	Table 805.3.1.1(2)	L2 Means of Egress, Stories with One Exit or Access to One Exit for Other Occupancies		Change in 2024 adds occupiable roofs, changes 1st occ load to 49, adds B and F to allowance for 100 feet exit access travel distance.	H	M	Further research on origin and impact of changes needed.	*				Further research needed.
8-25	8	804.5.1.2-804.10.2	804.4.1.2 - 804.12.2	805.3.1.2-805.11.2	L2 Means of Egress, Multiple Sections		2024, renumbered, including subsections.	N	N		A				Further research needed.
8-25.1	8	804.5.1.2.3	804.4.1.2.3	805.3.1.2.3	L2 Means of Egress, Fire Escapes, Dimensions		Renumbered.			Amend and add table to match 1311.504.4 in current MN code.	AM	AM	Y		
8-26	8	804.6.1.2	804.5.1.2	805.4.1.2	L2 Means of Egress, Egress Doorways, Group I-2		Change in 2021. I-2 Cond. 2 altered care suites comply with IBC 407.4.4-407.4.6.2.	H	M		A	A	Y		
8-27	8	804.6.4	804.5.4	805.4.4	L2 Means of Egress, Egress Doorways, Panic Hardware		Change in 2021. Adds compliance with IBC 1010.2.	H	M		A	A	Y		
8-28	8	804.7.3	804.6.3	805.5.3	L2 Means of Egress, Openings in Corridor Walls, Other Corridor Openings		Change in 2021. Adds option to protect openings per IBC 716.	H	M		A	A	Y		
8-29	8	804.8	804.7	805.6	L2 Means of Egress, Dead-End Corridors		Change in 2021. Adds I-2s with max 30 feet and adds I-2s to exceptions.	H	M		A	A	Y		
8-30	8	804.14.2		805.11.2	L2 Means of Egress, Guards, Design		Change in 2024. <i>Exception: In Group I-1 and I-2 facilities, required guards enclosing the occupiable roof areas shall be permitted to be greater than 48 inches (1219 mm) above the surface of the occupiable roof where the occupants, because of clinical needs, require restraint or containment as part of a function of a psychiatric or cognitive treatment area.</i>	H	L		A	A	Y		See IBC 503.1.4.1 & 1305.0503
8-31	8			1311.0806.2	L2 Structural, Existing Structural Elements Carrying Gravity Loads	Y	MN amendment. Priority to Structural TAG.				*				
8-32	8			1311.0806.3	L2 Structural, Existing Structural Elements Resisting Lateral Loads	Y	MN amendment. Priority to Structural TAG.				*				
8-33	8	805.3		806.3	L2 Structural, Existing Structural Elements Resisting Lateral Loads		Changes in 2024. Priority to Structural TAG.				*				

8-34	8	805.4		806.4	L2 Structural, Voluntary Lateral Force-Resisting System Alterations	Changes in 2024. Priority to Structural TAG.				*				
8-35	8	806.3	806.3		L2 Electrical, Health Care Facilities	New in 2021, I-2s, ambulatory care, outpatient clinics additions to electrical system install and equipment per NFPA 99.	H	L	CCLD Electrical Unit is aware of change.	A	A	Y		
8-36	8	808.1	808.1	809.1	L2 Plumbing, Health Care Facilities	New in 2021, I-2s, ambulatory care, outpatient clinics additions to med gas system install and equipment per NFPA 99.	H	L	Carry forward amendment currently at 809.1, but in 2024 at the exception at 1009.1 (use IBC Ch 29 for req'd number of fixtures). Also need to address med gas, send to IBC 427.	AM				
8-37	8	809.1	809.1	810.1	I2 Energy Conservation				Amendment needed to reference MR 1322 and 1323.	AM				
<b>Chapter 9 Alterations - Level 3</b>														
9-1	9	902.1		902.1	Work Area Method Level 3 Special Use and Occupancy, High-Rise Buildings	Change in 2024. Adds "or an occupiable roof" to scoping for 902.1.1 and 902.1.2.	M	N		A	A	Y		
9-2	9	902.2; 902.2.1			L3 Special Use and Occupancy, Conditions for I-1 Occupancies	New in 2024. Requires classification as Cond 1 or 2, provides for smoke barriers in I-1 Cond 2.	H	M		A	A	Y		
9-3	9	902.3			L3 Special Use and Occupancy, Ambulatory Care Facilities	New in 2024. Provides for smoke compartments and separation from other spaces if potential for four or more care recipients incapable of self-preservation at any time.	H	M		A	A	Y		
9-4	9	903.4	903.4		Enhanced Classroom Acoustics (Level 3 Alterations)	New in 2021. Requires enhanced acoustics in Group E with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.	H	M		A	A	Y		
9-5	9	904.1.4	904.1.4		L3 Automatic Sprinkler Systems, Specific Occupancy Groups	Change in 2021. Breaks out I occupancies into subgroups. For specific occupancy groups, revises (clarifies?) the exception for no water available-then smoke detection req.	H	M		A	A	Y		
9-6	9	904.1.5	904.1.5		L3 Automatic Sprinkler Systems, Group I-2	Change in 2021. Sprinkler reqs for I-2, Conditions 1 and 2.	H	M		A	A	Y		

9-7	9	904.1.6	904.1.6		L3 Windowless Stories		New in 2021. Work located in a windowless story, as determined in accordance with the IBC, shall be sprinklered where the work area is required to be sprinklered under the provisions of the IBC for newly constructed buildings and the building site has a sufficient municipal water supply for the design and installation of an automatic sprinkler system.	H	M		A	A	Y		
9-8	9	904.1.7	904.1.7	904.1.7	L3 Other Required Automatic Sprinkler Systems		Moved from 904.14 (2018) in 2021. Removes "that have exits or corridors shared by more than one tenant or that have exits or corridors serving an occupant load greater than 30."	L	L		A	A	Y		
9-9	9	904.1.8			L 3 Supervision and Alarms		New in 2024. Where an automatic sprinkler system is required by Sections 904.1.1 through 904.1.7, such systems shall be provided with supervision and alarms in accordance with Section 903.4 of the International Building Code.	H	M		A	A	Y		
9-10	9	905.4	905.4		L3 Two Way Communication Systems		New in 2021. In buildings with elevator service, a two-way communication system shall be provided where required by Section 1009.8 of the International Building Code.	H	M		A				Table 5/28. Coordinate with 1305. If exception for existing buildings accessible MOE is retained, this won't ever apply in existing building.
9-11	9	Section 906	Section 906	Section 906	L3 Structural		Changes in 2024, structural, mostly seismic related.			Send to Structural TAG.	*	A	Y		
9-11	9			1311.0907.1	L3 Energy Conservation	Y	Refers to MN Energy Codes for compliance.	N	N	Carry forward.	AM	A	Y		



9-12	9	Section 908			L3 Emergency Responder Communications Enhancement System Coverage		New in 2024. <b>908.1 Emergency responder communication enhancement system coverage.</b> The existing building shall undergo an evaluation of the emergency responder communication signal strength and coverage area within the entire building in accordance with Sections 908.1.1 and 908.1.2. <b>Exception:</b> Where it is determined by the fire code official that the emergency responder communication enhancement system (ERCES) is not needed. <b>908.1.1 Evaluation.</b> The evaluation shall determine the current signal strength and coverage capabilities of the public safety communication systems utilized by the jurisdiction, measured at the exterior of the building. <b>908.1.2 Compliance.</b> The evaluation report shall be submitted for approval by the fire code official and the frequency license holder. Where the coverage area, signal strength or DAQ does not comply with Section 510 of the International Fire Code, the existing building shall be provided with ERCES coverage. The fire code official is authorized to establish the timeframe for such installation or	H	M		A	A	Y		
------	---	-------------	--	--	---	--	---	---	---	--	---	---	---	--	--

**Chapter 10 Change of Occupancy**

10-1	10	1001.2; 1001.2.1; 1001.2.2; 1001.2.2.1	1001.2; 1001.2.1; 1001.2.2; 1001.2.2.1	1001.2; 1001.2.1; 1001.2.2; 1001.2.2.1	CoO, Certificate of Occupancy; Change of Use; Change of Occupancy Classification or Group		Change in 2024. Simplified language.	H	L		A	A	Y		
10-2	10	1002.1	1002.1	1002.1	CoO, Compliance with the Building Code		Change in 2021. Clarifies and replaces limited list of special occupancies with a reference to IBC Ch 4.	H	M		A	A	Y		
10-3	10	1002.2	1002.2		CoO, Incidental Uses		New in 2021. Directs change to incidental use to comply with IBC 509.	H	M		A	A	Y		
10-4	10	1002.3	1002.3		CoO, Change of Occupancy in Health Care		New in 2021, change to I-1 or I-2 comply with IBC. Exception added in 2024 for smoke barriers if not a Level 3 Alteration.	H	M		A	A	Y		

10-4	10	1002.4	1002.4		CoO, Storage		New in 2021. In Group I-2 occupancies, equipped throughout with an automatic sprinkler in per IBC 903.3.1.1, where a room 250 s.f. or less undergoes a change in occupancy to a storage room, the room shall be separated from the remainder of the building by construction capable of resisting the passage of smoke in accordance with IBC 509.4.2.	H	L		A	A	Y		
10-5	10	1004.1	1004.1	1004.1	CoO, Fire Protection, General		Change in 2024. Fire protection requirements in Section 1011 shall apply where <i>either of the following occur</i> : 1. A building or portion thereof undergoes a change of occupancy . 2. A building or portion thereof undergoes a change of occupancy and there is a different fire protection system threshold requirement in Chapter 9 of the current International Building Code than exists in the current building or portion thereof. <del>a building or portions thereof undergo a change of occupancy classification or where there is a change of occupancy within a space where there is a different fire protection system threshold requirement in Chapter 9 of the International Building Code.</del>	H	M		A	A	Y		
10-6	10			1311.1006.1	CoO, Structural, Live Loads	Y	MN amendment requires accounting for cumulative affects of additions and alterations since original construction.			Send to Structural TAG.	*				
10-7	10	1006.3	1006.3	1006.3	CoO, Seismic Loads		Seismic	N	N		A	A	Y		
10-8	10	1006.4	1006.4	1006.4	CoO, Access to Risk Cat. IV		Refers to seismic provisions of Ch. 3.	N	N		A	A	Y		
10-9	10	1007.1	1007.1	1007.1	CoO, Electrical		Change in 2021. Health care facilities , including Group I-2, ambulatory health care facilities and outpatient clinics comply with NFPA 70 and NFPA 99.	H	M		A	A	Y		
10-10	10			1311.1009	CoO, Plumbing, Increased Demand	Y	MN directs to MR 1305 (Ch 29) and MN Plumbing Code. Model code directs to IPC.	M	M	Carry forward.	AM	AM	Y		Amendment must to to IBC and MN Plumbing Code.

10-11	10	1009.1	1009.1	1009.1	CoO, Plumbing, Increased Demand		New exception in 2021. <i>Only where the occupant load of the story is increased by more than 20 percent, plumbing fixtures for the story shall be provided in quantities specified in the International Plumbing Code based on the increased occupant load.</i>	M	M	The 2021 IEBC code section 808 was relocated as the exception in section 1009.1. We had amended section 808 and need to carry that amendment forward to the new exception in 1009.1.	A	AM	Y		
10-12	10	1009.5	1009.5	1009.5	CoO, Plumbing, Group I-2		In 2021, adds <i>med gas system</i> to compliance with IPC.	H	M	Possibly need amendment to fire code/ IBC 427.	*	AM	Y		Reference IBC 427. Similar to 808.1.
10-13	10	1011.1	1011.1	1011.1	CoO, Change of Occupancy Classification, General		<i>Changes in 2024. The provisions of this section shall apply to buildings or portions thereof undergoing a change of occupancy classification. This includes a change of occupancy classification within a group as well as a change of occupancy classification from one group to a different group. <u>The provisions of this section shall also apply <del>or</del> where there is a change of occupancy within a space where building or portion thereof and there is a different fire protection system threshold requirement in Chapter 9 of the current International Building Code than exists in the current building or space.</u> Such buildings shall also comply with Sections 1002 through 1010 of this code.</i>	M	M		A	A	Y		
10-14				1311.1011.1.1	CoO, Change of Occupancy Classification, General, Compliance with Ch. 9	Y	MN amendment added "IEBC" Chapter 9 to clarify not meant to reference IBC Chapter 9. Compliance with Chapter 9 is not included as a section in 2021 or 2024.			Delete amendment.	D	Delete	Y		
10-15				1311.1011.2.1		Y	MN amendment changes "IBC" "to MN Rules Chapter 1305."			Delete amendment.	D	Delete	Y		

10-16		1011.2.1	1011.2.1	1011.2.1	CoO, Change of Occupancy Classification, Automatic Sprinkler System		In 2021 and 2024, Compliance with Chapter 9, 1011.1.1-1011.1.1.2 is eliminated. Section 1011.2 Fire Protection Systems is expanded in 2021 and rewritten in 2024. 2024 language: <i>The installation of an automatic sprinkler system shall be required where there is a change of occupancy classification and Chapter 9 of the current International Building Code requires an automatic sprinkler system based on the new occupancy or where there is a change of occupancy within the space where there is a different fire protection system threshold requirement in Chapter 9 of the current International Building Code than exists in the current building or space. The installation of the automatic sprinkler system shall be required within the area of the change of occupancy and areas of the building not separated horizontally and vertically from the change of occupancy by a nonrated permanent partition and horizontal assemblies, fire partition, smoke partition, smoke barrier, fire barrier or fire wall.</i>	M	L	Note that the model code does not require separations, walls or floors, to be rated.	A	A	Y		
10-17		1011.2.1.1; 1011.2.1.1.1			CoO, Change of Occupancy Classification, Nonrequired Automatic Sprinkler System; Approval		New in 2024.	M	L		A	A	Y		
10-18	10	1011.2.2	1011.2	1011.2.2	CoO, Change of Occupancy Classification, Fire Alarm and Detection Systems		Change in 2024 with language to clarify current IBC and current conditions in existing space.	M	M		A	A	Y		
10-19					CoO, Change of Occupancy Classification, Enhanced Classroom Acoustics		New in 2021. Where the work area is a Level 3 alteration, requires enhanced acoustics in Group E with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.	H	M		A	A	Y		
10-20	10			CCP-EB-9	Change of Occupancy Hazard Categories (Tables)		Proposed revision to 2024 IEBC Tables 1011.5, 1011.6, 1011.7, 2020 MBC Tables 1011.4, 1011.5, 1011.8.			See CCP-EB-9					Table until June 11 meeting to review CCPs.
10-21	10	1011.5.1	1011.5.1	1011.4.1	CoO, Change of Occupancy Classification, Means of Egress for Change to Higher Hazard Category		In 2021, Ex. 7 for existing operable windows changed to reference new 1011.5.6.	H	M	Amend to coordinate with 1305/7511.	AM*				Table-Coordinate with 1305/7511.

10-22	10	1011.5.1			CoO, Change of Occupancy Classification, Means of Egress for Change to Higher Hazard Category	In 2024, Ex. 8 added: <i>In Group I-1 and I-2 facilities, required guards enclosing the occupiable roof areas shall be permitted to be greater than 48 inches (1219 mm) above the surface of the occupiable roof where the occupants, because of clinical needs, require restraint or containment as part of a function of a psychiatric or cognitive treatment area.</i>	H	L		A	A	Y		
10-23	10	1011.5.2			CoO, Change of Occupancy Classification, Means of Egress for Change to an Equal or Lower Hazard Category	In 2024, Ex. 2 added: <i>In Group I-1 and I-2 facilities, required guards enclosing the occupiable roof areas shall be permitted to be greater than 48 inches (1219 mm) above the surface of the occupiable roof where the occupants, because of clinical needs, require restraint or containment as part of a function of a psychiatric or cognitive treatment area.</i>	H	L		A	A	Y		
10-24	10	1011.5.6	1011.5.6		CoO, Change of Occupancy Classification, Means of Egress for Change to an Equal or Lower Hazard Category, Existing Emergency Escape and Rescue Openings	Added in 2021. <i>Where a change of occupancy would require an emergency escape and rescue opening in accordance with Section 1031 of the International Building Code, operable windows serving as the emergency escape and rescue opening shall comply with the following:</i> <ol style="list-style-type: none"> <li>1. <i>An existing operable window shall provide a minimum net clear opening of 4 square feet with a minimum net clear opening height of 22 inches and a minimum net clear opening width of 20 inches.</i></li> <li>2. <i>A replacement window where such window complies with both of the following:</i> <ol style="list-style-type: none"> <li>2.1. <i>The replacement window meets the size requirements in Item 1.</i></li> <li>2.2. <i>The replacement window is the manufacturer's largest standard size window that will fit within the existing frame or existing rough opening. The replacement window shall be permitted to be of the same operating style as the existing window or a style that provides for an equal or greater window opening area than the existing window.</i></li> </ol> </li> </ol>	H	M	Amend to match 1305, 7511, other similar sections in 1311.	AM				Table-Coordinate with 1305/7511 for licensed facilities.

10-25	10	1011.6.1	1011.6.1	1011.5.1	CoO, Change of Occupancy Classification, Heights and Areas for Change to a Higher Hazard Category	Ex. 2 added in 2024. <i>Buildings that were constructed in compliance with a previously issued permit that have floor assemblies with a 1-1/2-hour fire resistance rating shall not be required to comply with Chapter 5 of the International Building Code where all of the following apply:</i> <i>2.1 Chapter 5 of the International Building Code requires Type IB construction.</i> <i>2.2 The building does not include Group H occupancies.</i> <i>2.3 The building is protected throughout with an automatic sprinkler system in accordance Section 903.3.1.1 of the International Building Code.</i>	H	M		A	A	Y		
10-26	10	1011.7.1	1011.7.1	1011.6.1	CoO, Change of Occupancy Classification, Exterior Wall Rating for Change of Occupancy to a Higher-Hazard Category	Changed in 2024, adding req. for compliance with exterior opening areas per IBC.	M	M		A	A	Y		
10-27	10	1011.8.2	1011.8.2	1011.7.2	CoO, Change of Occupancy Classification, Enclosure of Vertical Shafts, Stairways	Exception 2 revised 2024: <i>Unenclosed existing stairways need not be enclosed in a continuous vertical shaft if each story is separated from other stories by 1-hour fire-resistance-rated construction or approved wired glass set in steel frames and all exit corridors are sprinklered in accordance with the International Building Code . The openings between the corridor and the <del>tenant occupant</del> space shall have not fewer than one sprinkler head above the openings on the tenant side. <del>The sprinkler system shall be permitted to be supplied from the domestic water supply systems, provided that the system is of adequate pressure, capacity and sizing for the combined domestic and sprinkler requirements in accordance with the International Building Code.</del></i>	M	M		A	A	Y		
<b>Chapter 11 Additions</b>														
11-1	11	1101.2; 1102.3	1101.2	1101.2	Additions, Creation or Extension of Nonconformity	Revised and added exception in 2024. 1101.3 is new in 2024. All structural.			Send to Structural TAG.	*				

11-2	11	1101.5			Additions, Smoke Barriers in Group I-1, Condition 2		New in 2024. Where an addition to an existing Group I-1, Condition 2 building adds sleeping areas that result in more than 50 care recipients on a story, smoke barriers shall be provided to subdivide such story into not fewer than two smoke compartments in accordance with Section 420.6 of the International Building Code. Exception: Where the existing building is divided into smoke compartments and the addition does not result in any individual smoke compartment exceeding the size and travel distance requirements in Section 420.6 of the International Building Code, additional smoke barriers are not required.	H	M		A	A	Y		
11-3	11	1101.6	1101.4		Additions, Enhanced Classroom Acoustics		New in 2021. Where the work area is a Level 3 alteration, requires enhanced acoustics in Group E with a volume of 20K cf or less. Applies ICC A117.1 808 accessibility standard for reverberation only.	H	M		A	A	Y		
11-4	11	1102.3	1102.3	1102.3	Additions, Heights and Areas, Fire Protection Systems		Exception added 2024. Nonoccupiable appendages, such as elevator and exit stairway shafts, shall be permitted beyond that permitted by the International Building Code.	M	M		A	A	Y		
11-5				1311.1103.1	Additions - Structural - Additional Gravity Loads	Y	Increase of demand-capacity ratio (cumulative) to >105% requires replacement or alteration. (additional provisions - see full text).			Send to Structural TAG.		A	Y		
11-6				1311.1103.2	Additions - Structural - Lateral Force-Resisting Systems	Y	Increase in demand-capacity ratio (cumulative) to <= 110% may remain unaltered, considered per IBC 1609.			Send to Structural TAG.		A	Y		
11-7	11	1103.2	1103.2	1103.2	Additions, Lateral force-resisting systems		Changes in 2024. All structural.			Send to Structural TAG.	*				
11-8	11	1103.3	1103.3		Flood hazard.		Changes in 2024. MR 1335 is applicable.	N	N		A	A	Y		
11-9		308		1311.1105.1	Additions, Carbon Monoxide Alarms in I-1, I-2, I-4, and R		Additions trigger CO Alarms throughout per IBC 915.	H	N	This is now in 308.	AM				
11-10	11	303.2		1311.1106.1	Additions, Storm Shelters, Group E Occupancy		Addition w/ occ load 50+ requires storm shelter per ICC 500.	H	N	This requirement is now in Chapter 3, 303.2. Add Mower County.	AM				

**Chapter 12 - Historic Buildings**

12-1	12			1311.1201.2	Historic Buildings, Report		A historic building undergoing alteration or change of occupancy shall be investigated and evaluated. A written report shall be prepared and filed with the code official by a registered design professional when such a report is necessary in the opinion of the code official. The report shall identify each required safety feature that is in compliance with this chapter and where compliance with provisions of this chapter would be damaging to the contributing historic features.	M	M		AM				
12-2	12	1201.2	1201.2	1201.2	Historic Buildings, Report		Changes in 2024. Some language changes. Adds - <i>Exception: An investigation, evaluation and report shall not be required where the alteration is scoped by Section 602 as a Level 1 alteration and does not make the building or structure less compliant with the provisions of the IBC.</i>	M	L		A				
12-3	12	1201.3	1201.3	1201.3	Historic Buildings, Special Occupancy Exceptions-Museums		Changes in 2024. Clarifies 3000 sf is per floor, changes doors in "open position" to "unlocked position".	M	M		A				
12-4	12	1203.2; 1203.12	1203.2; 1203.12	1203.2; 1203.12	Historic Buildings, Fire Safety		In 2024, changes "fire extinguishing" system to "sprinkler" system.	H	M		A				
12-5	12	1203.3	1203.3	1203.3	Historic Buildings, Fire Safety, Means of Egress		2024, clarifying language change re existing door openings, corridors, and stairway widths.	M	M		A				



12-6	12	1204.9	1204.9	1204.9	Historic Buildings, Interior Finishes	<p>Change in 2021. New language: <i>Where interior finish materials are required to comply with the fire test requirements of Section 803.1 of the IBC, existing nonconforming materials shall be permitted to be surfaced with an approved fire-retardant coating to achieve the required classification. Compliance with this section shall be demonstrated by testing the fire-retardant coating on the same material and achieving the required fire classification. Where the same material is not available, it shall be permitted to test on a similar material.</i></p> <p>Exception: Existing nonconforming materials need not <i>be surfaced with an approved fire-retardant coating</i> where the building is equipped throughout with an automatic sprinkler system installed in accordance with the IBC and the nonconforming materials can be substantiated as being historic in character.</p>	M	M		A				
12-7	12	1205.1	1205.1	1205.1	Historic Buildings - Structural - General	<p>Change in 2024. Now reads: Historic buildings shall comply with the applicable structural provisions for the work as classified in Chapter 4 or 6-</p> <p>Exceptions:</p> <ol style="list-style-type: none"> <li>The code official shall be authorized to accept existing floor and previously approved live loads and roof live loads and to approve operational controls that limit the live load or roof live load.</li> <li>Regardless of the level of damage, structural repairs shall be permitted to return the building to its predamage condition without additional work.</li> </ol>			Sent to Structural TAG.	*				
<b>Chapter 13 - Performance Compliance Methods (PCM)</b>														
13-1	13	1301.1	1301.1	1301.1	PCM, Scope	<p>Change in 2021. Now specifies except where compliance with Ch 5 or Work Area methods is required in Ch 13.</p>	M	M						

13-2	13			1311.1301.2	PCM, Applicability		In amendment, "Structures existing prior to the effective date of this code, in which there is work involving..." replaces model code language: "Existing buildings in which there is work involving..."	M	M	Carry forward.	AM				
13-3	13	1301.2.1	1301.2	1301.2	PCM, Applicability		Change in 2021. Adds "These <i>provisions shall also apply to Group U occupancies where such occupancies are undergoing a change of occupancy or a partial change in occupancy with separations in accordance with Section 1302.1.2. These provisions shall not apply</i> to buildings with occupancies in Group H, I-1, I-3 or I-4."	M	M		A				
13-4	13			1311.1301.3.1	PCM, Hazards		Amendment adds Minnesota-specific references (MR 1300, MS 463.15 to 463.26).	M	M	Carry forward.	AM				
13-5	13			1311.3.2	PCM, Compliance with Other Codes		Amendment deletes section.	N	N	Carry forward.	AM				
13-6	13	1301.2.6	1301.2.6		PCM, Plumbing Fixtures		New in 2021. Refers to 1009 for Change of Occ and 808 for alterations. Points to IPC for additions.	N	N		A				
13-7		1303.1.3	1301.3.3	1301.3.3	PCM, Acceptance		Revised 2024. MR 1335 applies.	N	N		A				
13-8	13	1305.2.2	1301.6.2.1	1301.6.2.1	PCM, Evaluation Process, Building Area			M	M		A				
13-9		1305.2.2.2	1301.6.2.2		PCM, Area Formula		Revised in 2021.	M	M		A				
13-10		Table 1305.2.3	Table 1301.6.3	Table 1301.6.3	PCM, Compartmentation Values Table		In 2021, added footnote a regarding interpolation and added row for I-2.	H	M		A				
13-11		1305.2.3.1	1301.6.3.1		PCM, Compartmentation Categories		New in 2021.	M	M		A				
13-12		1305.2.4	1301.6.4	1301.6.4	PCM, Tenant and Dwelling Unit Separations		Revised in 2021. Changes "patient" to " <i>care recipient</i> ". Adds " <i>The value shall be zero for single tenant buildings and buildings without dwelling units.</i> "	N	N		A				
13-13		1305.2.5.1	1301.6.5.1	1301.6.5.1	PCM, Corridor Walls, Categories		Revised in 2021. Slight change to Item 3, Category c.	M	N		A				
13-14		1305.2.7	1301.6.7.1	1301.6.7.1	PCM, HVAC, Categories		Revised 2021. Change removes "connected" to qualifier for Category e, Item 5.	M	L		A				
13-15		1305.2.17	1301.6.17	1301.6.17	PCM, Automatic Sprinklers		Revised 2021. Adds "or control" to "suppress". Required sprinklers is per IBC.	H	L		A				
13-16		1305.2.17.1	1301.6.17.1	1301.6.17.1	PCM, Automatic Sprinklers, Categories		Changes to all categories in 2021.	H	L		A				
13-17		Table 1305.2.20.1	Table 1301.6.20	Table 1301.6.20	PCM, Smoke Compartmentation Values		2021, revised values for I-2.	H	L		A				

13-18		1305.2.20.1	1301.6.20.1	1301.6.20.1	PCM, Smoke Compartmentation, Categories		Changes in 2021 to Categories a and b, referencing 407.5 of the IBC.	H	L		A				
13-19		1305.2.21 and all subsections	1301.6.21 and all subsections	1301.6.21 and subsections	PCM, Care Recipient Ability, Concentration, Smoke Compartment Location, and Ratio to Attendant		Changes to all subsections in 2021.	H	M		A				
13-20		Table 1306.1	Table 1301.7	Table 1301.7	PCM, Building Score, Summary Sheet		Change in 2021 replaces "patient" with "care recipient".	H	N		A				
13-21		1307.1.1	1301.9.1	1301.9.1	PCM, Evaluation of Building Safety, Mixed Occupancies		Change in 2021. Adds to the end of Item 2: <i>An evaluation is not required for areas of the building with separated occupancies in accordance with Table 508.4 of the International Building Code in which there are no alterations or change of occupancy.</i>	H	L		A				
<b>Chapter 14 - Relocated Buildings</b>															
14-1	14	1401.1.1	1401.1.1		Relocated or Moved Buildings, Bleachers		New in 2021 - relocated comply with ICC 300.	M	M		A				
14-2	14	1401.2		1311.1401.2	Relocated Buildings, Conformance		References MR 1300.0180.	L	L		AM				
14-3	14	1402.3		1311.1402.3	Relocated Buildings, Wind Loads					Send to Structural TAG	*				
14-4	14	1402.5		1311.1402.5	Relocated Buildings, Snow Loads					Send to Structural TAG	*				