

[Link to 2024 IEBC \(changes in blue\)](#)

[Link to 2021 IEBC \(changes in blue\)](#)

| To Be Completed by TAG Leads | | | | | | | | | | | TAG Meeting Results | | | | |
|---|-------------------|------------------------|------------------------|----------------------|--|---------------|---|----------------------------------|-------------|---|--|--------------------|---------------------|-----------------------|--|
| Blue - Current MN Amendment Purple - Code Change Proposal | | | | | | | | | | | Recommendations: A - Accept Model Code AM - Amend Model Code D - Delete MN Amendment R - Reject WD - CCP Withdrawn | | | | |
| Item Number | 2024 IEBC Chapter | 2024 IEBC Code Section | 2021 IEBC Code Section | 2020 MN Code Section | Code Section Heading/Topic | MN Amendment? | Description of change(s) to code language | Safety/Health Value | Cost Impact | Staff Comment | Staff Recommendation | TAG Recommendation | TAG Group Consensus | Stakeholder Consensus | Comments |
| | | | | | | | | N - None, L - Low, M-Med, H-High | | | | | Y or N | Y or N | |
| 1311.0010 Adoption and 1311.0020 References to other Codes | | | | | | | | | | | | | | | |
| 0-3 | | | | CCP-EB-11 | References to Other Codes - Fire Code | | Proposes reference to IFC mean to MN Fire Code. | | | | | | | | Review at June 11 meeting. 6/11 review at future meeting |
| 0-4 | | | | CCP-EB-10 | References to Other Codes - Residential Code | | Proposes to make Conservation Code applicable to IRC/1309 buildings. Revision to 1300.0020 Subp. 9. | | | | | | | | Review at June 11 meeting. 6/11 review at future meeting |
| Chapter 3 Provisions for All Compliance Methods | | | | | | | | | | | | | | | |
| 3-12.1 | 3 | | | 1311.0503.14 | | y | Smoke alarm code sections from other chapters moved to 307. Carry amendment to new smoke alarm location. Renumber to 1311.0307. Amendment points to 1305. | No change. | No change. | (coordinate with 1305 and 1309 TAGs). <u>Needs to be deleted, now covered in amendment to 307.1.</u> | AM* | | | | |
| 3-14 | 3 | 308 | 308.1 | 1311.0503.15 | Carbon Monoxide Detection (Moved) | y | Section relocated here in 2021, revision for I-2s in 2024 in exception #4. Added 'E's' in 2021. Removed specific occupancies in the 2024 and changed wording to existing buildings. | H | N | The current amendment to 503.15 should be applied here in Ch 3. Propose amending reference to IBC instead of IFC/IRC and deleting exception #3 (coordinate with 1305 and 1309 TAGs) | AM* | | | | |
| 3-14.1 | 3 | | | 1311.0503.15 | Carbon Monoxide Alarms | Y | Carry amendment from Ch 5 to new location in Ch 3. | H | N | (coordinate with 1305 and 1309 TAGs). | AM* | | | | |
| Chapter 5 Prescriptive Compliance Method | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | |
|--|----|---------|---------|--------------|--|---|---|---|---|---|-----|--|--|--|---|
| 5-19 | 5 | | | 1311.0503.14 | Smoke Alarms in Existing Portions of a Building (Alterations) - Relocated to 307.1 | Y | Smoke alarms relocated to 307.1 in 2021. See also CCP-EB-1. One exception added. | H | L | Current amendment to 503.14 not needed here 307.1 needs this amendment. This will be addressed with CC-EB-1 in Ch 3, so this will effectively be deleted. | AM | | | | |
| 5-19.1 | 5 | | | 1311.0503.15 | Carbon Monoxide Alarms | Y | CO alarms relocated to 308 in 2021. Two exceptions added. | H | L | Current amendment to 503.15 not needed here. 308 needs amendment. | AM | | | | |
| 5-31.1 | 5 | | | CCP-EB-8 | Table - Prescriptive Life Safety & Fire Risk | | Proposed revision to MR Table 506.1 | H | L | Review 2018 SONAR for the original amendment. | | | | | Table until 5/11 meeting to review CCPs. 6/11 - keep tabled review at future meeting. |
| 5-33 | 5 | 506.4 | 506.4 | | Existing Emergency Escape and Rescue Openings (Change of Occupancy) | | Added to 506 Change of Occupancy in 2021. | H | M | Coordinate with 1305 and 7511. | AM* | | | | Carried forward to future meeting. |
| Chapter 7 Alterations - Level 1 | | | | | | | | | | | | | | | |
| 7-4 | 7 | 702.5 | | 1311.0702.5 | Replacement Window Emergency Escape and Rescue Openings; Licensed Facilities | Y | Amends and adds subsection 702.5.1. Removes reference to IRC buildings; combines window opening control devices (found in subsection 702.5.1 in model codes) to main section. Added subsection 702.5.1 addresses foster care or day care licensed or registered by state of MN. | H | L | Insert current MCCEB amendment 702.5.1 Licensed facilities into the 2024 IEBC at 702.6 and renumber 702.6 Bars, grilles, covers or screens to 702.7. Also renumber Sections 702.7 Materials and methods and 702.7.1 International Fuel Gas Code to 702.8 and 702.8.1. Carry over first part of amendment, second part not needed. | AM* | | | | Tabled 5/14 for comparison/coordination with 7511 and 1305 TAGs and DoH reqs. |
| 7-5 | 7 | 702.5.1 | 702.5.1 | | Control Devices (Replacement EEROs) | | New sub-section for control devices for replacement EEROs added in 2021. | H | L | | A | | | | Tabled 5/14 for comparison/coordination with 7511 and 1305 TAGs and DoH reqs. |
| 10-20 | 10 | | | CCP-EB-9 | Change of Occupancy Hazard Categories (Tables) | | Proposed revision to 2024 IEBC Tables 1011.5, 1011.6, 1011.7, 2020 MBC Tables 1011.4, 1011.5, 1011.8. | | | See CCP-EB-9 | | | | | Table until June-14 25 meeting to review CCPs. 6/11 review at future |
| 11-9 | | 308 | | 1311.1105.1 | Additions, Carbon Monoxide Alarms in I-1, I-2, I-4, and R | | Additions trigger CO Alarms throughout per IBC 915. | H | N | This is now in 308. | AM | | | | |

| | | | | | | | | | | | | | | |
|--|----|-----------------|-----------------|-----------------|--|--|---|---|--|----|--|--|--|--|
| 11-10 | 11 | 303.2 | | 1311.1106.1 | Additions, Storm Shelters, Group E Occupancy | Addition w/ occ load 50+ requires storm shelter per ICC 500. | H | N | This requirement is now in Chapter 3, 303.2. Add Mower County. | AM | | | | |
| Chapter 12 - Historic Buildings | | | | | | | | | | | | | | |
| 12-1 | 12 | | | 1311.1201.2 | Historic Buildings, Report | A historic building undergoing alteration or change of occupancy shall be investigated and evaluated. A written report shall be prepared and filed with the code official by a registered design professional when such a report is necessary in the opinion of the code official. The report shall identify each required safety feature that is in compliance with this chapter and where compliance with provisions of this chapter would be damaging to the contributing historic features. | M | M | | AM | | | | |
| 12-2 | 12 | 1201.2 | 1201.2 | 1201.2 | Historic Buildings, Report | Changes in 2024. Some language changes. Adds - <i>Exception: An investigation, evaluation and report shall not be required where the alteration is scoped by Section 602 as a Level 1 alteration and does not make the building or structure less compliant with the provisions of the IBC.</i> | M | L | | A | | | | |
| 12-3 | 12 | 1201.3 | 1201.3 | 1201.3 | Historic Buildings, Special Occupancy Exceptions-Museums | Changes in 2024. Clarifies 3000 sf is per floor, changes doors in "open position" to "unlocked position". | M | M | | A | | | | |
| 12-4 | 12 | 1203.2; 1203.12 | 1203.2; 1203.12 | 1203.2; 1203.12 | Historic Buildings, Fire Safety | In 2024, changes "fire extinguishing" system to "sprinkler" system. | H | M | | A | | | | |
| 12-5 | 12 | 1203.3 | 1203.3 | 1203.3 | Historic Buildings, Fire Safety, Means of Egress | 2024, clarifying language change re existing door openings, corridors, and stairway widths. | M | M | | A | | | | |
| 12-6 | 12 | 1204.9 | 1204.9 | 1204.9 | Historic Buildings, Interior Finishes | Change in 2021. New language: <i>Where interior finish materials are required to comply with the fire test requirements of Section 803.1 of the IBC, existing nonconforming materials shall be permitted to be surfaced with an approved fire-retardant coating to achieve the required classification. Compliance with this section shall be demonstrated by testing the fire-retardant coating on the same material and achieving the required fire classification. Where the same material is not available, it shall be permitted to test on a similar material.</i> Exception: Existing nonconforming materials need not <i>be surfaced with an approved fire-retardant coating</i> where the building is equipped throughout with an automatic sprinkler system installed in accordance with the IBC and the nonconforming materials can be substantiated as being historic in character. | M | M | | A | | | | |

| Chapter 13 - Performance Compliance Methods (PCM) | | | | | | | | | | | | | | |
|---|----|-------------------|-----------------|-----------------|---|---|---|---|----------------|----|--|--|--|--|
| 13-1 | 13 | 1301.1 | 1301.1 | 1301.1 | PCM, Scope | Change in 2021. Now specifies except where compliance with Ch 5 or Work Area methods is required in Ch 13. | M | M | | A | | | | |
| 13-2 | 13 | | | 1311.1301.2 | PCM, Applicability | In amendment, "Structures existing prior to the effective date of this code, in which there is work involving..." replaces model code language: "Existing buildings in which there is work involving...". | M | M | Carry forward. | AM | | | | |
| 13-3 | 13 | 1301.2.1 | 1301.2 | 1301.2 | PCM, Applicability | Change in 2021. Adds "These <i>provisions shall also apply to Group U occupancies where such occupancies are undergoing a change of occupancy or a partial change in occupancy with separations in accordance with Section 1302.1.2. These provisions shall not apply</i> to buildings with occupancies in Group H, I-1, I-3 or I-4." | M | M | | A | | | | |
| 13-4 | 13 | | | 1311.1301.3.1 | PCM, Hazards | Amendment adds Minnesota-specific references (MR 1300, MS 463.15 to 463.26). | M | M | Carry forward. | AM | | | | |
| 13-5 | 13 | | | 1311.3.2 | PCM, Compliance with Other Codes | Amendment deletes section. | N | N | Carry forward. | AM | | | | |
| 13-6 | 13 | 1301.2.6 | 1301.2.6 | | PCM, Plumbing Fixtures | New in 2021. Refers to 1009 for Change of Occ and 808 for alterations. Points to IPC for additions. | N | N | | A | | | | |
| 13-7 | | 1303.1.3 | 1301.3.3 | 1301.3.3 | PCM, Acceptance | Revised 2024. MR 1335 applies. | N | N | | A | | | | |
| 13-8 | 13 | 1305.2.2 | 1301.6.2.1 | 1301.6.2.1 | PCM, Evaluation Process, Building Area | | M | M | | A | | | | |
| 13-9 | | 1305.2.2.2 | 1301.6.2.2 | | PCM, Area Formula | Revised in 2021. | M | M | | A | | | | |
| 13-10 | | Table 1305.2.3 | Table 1301.6.3 | Table 1301.6.3 | PCM, Compartmentation Values Table | In 2021, added footnote a regarding interpolation and added row for I-2. | H | M | | A | | | | |
| 13-11 | | 1305.2.3.1 | 1301.6.3.1 | | PCM, Compartmentation Categories | New in 2021. | M | M | | A | | | | |
| 13-12 | | 1305.2.4 | 1301.6.4 | 1301.6.4 | PCM, Tenant and Dwelling Unit Separations | Revised in 2021. Changes "patient" to " <i>care recipient</i> ". Adds " <i>The value shall be zero for single tenant buildings and buildings without dwelling units.</i> " | N | N | | A | | | | |
| 13-13 | | 1305.2.5.1 | 1301.6.5.1 | 1301.6.5.1 | PCM, Corridor Walls, Categories | Revised in 2021. Slight change to Item 3, Category c. | M | N | | A | | | | |
| 13-14 | | 1305.2.7 | 1301.6.7.1 | 1301.6.7.1 | PCM, HVAC, Categories | Revised 2021. Change removes "connected" to qualifier for Category e, Item 5. | M | L | | A | | | | |
| 13-15 | | 1305.2.17 | 1301.6.17 | 1301.6.17 | PCM, Automatic Sprinklers | Revised 2021. Adds "or control" to "suppress". Required sprinklers is per IBC. | H | L | | A | | | | |
| 13-16 | | 1305.2.17.1 | 1301.6.17.1 | 1301.6.17.1 | PCM, Automatic Sprinklers, Categories | Changes to all categories in 2021. | H | L | | A | | | | |
| 13-17 | | Table 1305.2.20.1 | Table 1301.6.20 | Table 1301.6.20 | PCM, Smoke Compartmentation Values | 2021, revised values for I-2. | H | L | | A | | | | |
| 13-18 | | 1305.2.20.1 | 1301.6.20.1 | 1301.6.20.1 | PCM, Smoke Compartmentation, Categories | Changes in 2021 to Categories a and b, referencing 407.5 of the IBC. | H | L | | A | | | | |

| | | | | | | | | | | | | | | |
|-------|----|-------------------------------|-------------------------------|---------------------------|--|--|---|---|--|--------|--|--|--|--|
| 13-19 | | 1305.2.21 and all subsections | 1301.6.21 and all subsections | 1301.6.21 and subsections | PCM, Care Recipient Ability, Concentration, Smoke Compartment Location, and Ratio to Attendant | Changes to all subsections in 2021. | H | M | | A | | | | |
| 13-20 | | Table 1306.1 | Table 1301.7 | Table 1301.7 | PCM, Building Score, Summary Sheet | Change in 2021 replaces "patient" with "care recipient". | H | N | | A | | | | |
| 13-21 | | 1307.1.1 | 1301.9.1 | 1301.9.1 | PCM, Evaluation of Building Safety, Mixed Occupancies | Change in 2021. Adds to the end of Item 2: <i>An evaluation is not required for areas of the building with separated occupancies in accordance with Table 508.4 of the International Building Code in which there are no alterations or change of occupancy.</i> | H | L | | A | | | | |
| 14-1 | 14 | 1401.1.1 | 1401.1.1 | | Relocated or Moved Buildings, Bleachers | New in 2021 - relocated comply with ICC 300. | M | M | | A | | | | |
| 15-1 | 15 | Section 15 | | | Construction Safeguards | | | | | AM (D) | | | | |