




What's wrong with this picture?

No fall protection while setting pre-stressed concrete at a height of more than six feet



What's wrong with this picture?

Worker exposed to burns from molten metal without wearing flame-retardant personal protective clothing



What's wrong with this picture?

Working on a scaffold higher than 10 feet without any fall protection



What's wrong with this picture?

Working over water without a personal flotation device



What's wrong with this picture?

Worker exposed to fall of more than six feet with no fall protection



What's wrong with this picture?

Worker exposed to fall of more than six feet with no fall protection



What's wrong with this picture?

Working on a scaffold higher than 10 feet without any fall protection



What's wrong with this picture?

**Working outside of the guardrails
on an aerial lift**



What's wrong with this picture?

Walking on the top plate higher than six feet with no fall protection and working on a carpenter's bracket scaffold higher than 10 feet with no fall protection



What's wrong with this picture?

Standing on the top plate that is more than six feet high without fall protection



What's wrong with this picture?

Working on a scaffold higher than 10 feet without any fall protection



What's wrong with this picture?

No personal fall-arrest system for worker being lifted by a personnel elevating platform supported by a rough terrain forklift



What's wrong with this picture?

Workers on a roof greater than 25 feet from eave to ground with no fall protection